

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010292/AQCE2

Date: 25/02/2022

REFERENCE

Insured/Claimant:	YU QIAN	Policy No:	7210002173		
Date of Loss:	22/09/2021	Nature of Claim:	OD	Claim No:	6612009651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4006C		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM027753
Reg. Date:	11/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF56MA015362
Colour:	Blue	Odometer:	5259 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,420.00	6,466.96	3,953.04	37.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,052.00	10,077.00	5,975.00	37.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,472.00	16,543.96	9,928.04	37.50
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	24,872.00	14,943.96	9,928.04	39.92
+ GST 7.00/7.00% (S\$)	1,741.04	1,046.08	694.96	39.92
Nett Amount (S\$)	26,613.04	15,990.04	10,623.00	39.92

INSPECTION

Date of Assignment:	06/10/2021		
Date Inspected:	05/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,451.00 FS	*1,960.80 FS
2	1		*REAR BUMPER SECURING STRIP	Not Necessary	112.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	223.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
5	1		*REAR BUMPER LIGHT REFLECTOR - RH OUTER	Not Necessary	43.00 FS	*- FS
6	1		*REAR LED TAIL LIGHT - RH	Not Necessary	1,142.00 FS	*- FS
7	1		*REAR LED TAIL LIGHT TRIM - RH	Not Necessary	30.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	44.00 FS	*- FS
9	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	46.00 FS	*- FS
10	1		*REAR FENDER - RH	Dented	3,791.00 FS	*3,032.80 FS
11	1		*REAR QUARTER GLASS - RH	Necessary	717.00 FS	*573.20 FS
12	1		*REAR SILL PANEL ATTACHMENT PARTS - RH	Not Necessary	130.00 FS	*- FS
13	1		*REAR SILL PANEL ADHESIVE TAPE - RH	Not Necessary	212.00 FS	*- FS
14	1		*QUARTER GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
15	1		*ARYCLIX SEALANT	Necessary	180.00 FS	*180.00 FS
16	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
18	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
19	1		*SUNDRIES	Necessary	350.00 FS	*20.16 FS
						F=Franchise part. S=SpcNett.
					Total Parts (\$\$)	10,420.00 6,466.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR RHS SIDE 1/4 GLASS	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL APNEL, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	5,000.00	2,475.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
Gross Labour Cost (\$\$)			16,052.00	10,077.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >