

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21010293/Vty3e2	
	8 SHENTON WAY TOWERSINGAPOR			Date:	14/10/2021	
	ATTN: LOH CYNTH	HIA		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 2154X	Veh. Inspected		PC 3923L	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S1M03JED	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		06/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE COMMUTER	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	KDH2230023665	Colour		WHITE	
	Odometer	427845 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	MICHELIN		5 mm	
	L/H Front Tyre	195 R15C	MICHELIN		5 mm	
	R/H Rear Tyre	195 R15C	MICHELIN		5 mm	
	L/H Rear Tyre	195 R15C	MICHELIN		5 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	05/10/2021	Inspect Date / T	Γime	06/10/2021 ( 11:30 AM )	
	Survey held at GARAGE 13 PTE LTD					
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21010293/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser