

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010296/AQY3E2

Date: 10/05/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00009942100  
Claimant Vehicle No: SMH3356H Insured Vehicle No: SMP3986Y  
Date of Loss: 30/09/2021 Nature of Claim: TP Claim No: SNM21D205608/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH3356H  
Make & Model: RENAULT SCENIC III, 1.5 (A) Engine No: K9KF649D038616  
Reg. Date: 18/01/2019 (Man. Year: 2018) Chassis No: VF1RFA00260211851  
Colour: Blue Odometer: 46475 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,053.22	3,017.07	25,036.15	89.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	1,030.00	3,620.00	77.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>32,703.22</b>	<b>4,047.07</b>	<b>28,656.15</b>	<b>87.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>(S\$)</b>	32,703.22	3,200.00	29,503.22	90.22
<b>+ GST 7.00/7.00% (S\$)</b>	2,289.23	224.00	2,065.23	90.22
<b>Nett Amount (S\$)</b>	<b>34,992.45</b>	<b>3,424.00</b>	<b>31,568.45</b>	<b>90.22</b>

### INSPECTION

Date of Assignment: 05/10/2021  
Date Inspected: 06/10/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)  
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT  
Singapore 415875  
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2022)
<b>Parts:</b>	M1-MPV	RENAULT SCENIC III 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH3356H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	5,854.00 FL	*- FL
2	1		*TAILGATE OUTER COVER	Repair	1,512.00 FL	*- FL
3	1		*TAILGATE WINDSCREEN WITH MOULDING	Not Necessary	1,845.00 FL	*- FL
4	1		*TAILGATE EMBLEM (SCENIC)	Necessary	122.00 FL	*122.00 FL
5	1		*TAILGATE OUTER CHROME	Not Necessary	485.00 FL	*- FL
6	1		*REVERSE CAMERA	Not Necessary	1,542.00 FL	*- FL
7	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	308.00 FL	*- FL
8	1		*TAILGATE OPENER SWITCH	Not Necessary	217.90 FL	*- FL
9	2		*TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
10	1		*TAILGATE INNER LOCK	Not Necessary	685.00 FL	*- FL
11	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Not Necessary	385.00 FL	*- FL
13	1		*TAILGATE LOCK DETECTOR	Cracked	452.00 FL	*195.00 FL
14	2		*TAIL LAMP	Not Necessary	1,370.00 FL	*- FL
15	2		*TAIL LAMP BOTTOM RETAINER	Not Necessary	316.00 FL	*- FL
16	1		*REAR BUMPER	Deformed	2,145.00 FL	*1,152.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Cracked	336.00 FL	*336.00 FL
18	1		*REAR BUMPER CENTER RETAINER	Cracked	217.30 FL	*217.30 FL
19	1		*REAR BUMPER REINFORCEMENT	Not Necessary	874.00 FL	*- FL
20	1		*REAR BUMPER DIFFUSER	Deformed	698.00 FL	*320.00 FL
21	2		*REAR BUMPER REFLECTOR	Cracked	708.00 FL	*420.00 FL
22	2		*REAR BUMPER SIDE BOTTOM BRACKET	Not Necessary	308.00 FL	*- FL
23	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	1,576.00 FL	*490.00 FL
24	1		*REVERSE SENSOR WIRING	Not Necessary	685.00 FL	*- FL
25	1		*END PANEL	Not Necessary	1,245.00 FL	*- FL
26	1		*END PANEL TOP TRIM	Not Necessary	288.70 FL	*- FL
27	1		*REAR FLOOR PANEL	Not Necessary	896.50 FL	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	842.00 FL	*- FL
29	1		*REAR FLOOR CENTER BOARD	Not Necessary	546.00 FL	*- FL
30	1		*REAR FLOOR PANEL TOOL SPONGE	Not Necessary	355.00 FL	*- FL
31	2		*REAR FENDER INNER TRIM	Not Necessary	1,314.00 FL	*- FL
32	2		*REAR FENDER INNER SHIELD	Not Necessary	397.40 FL	*- FL
33	2		*REAR FENDER AIR VENT	Not Necessary	170.00 FL	*- FL
34	1		*REAR EXHAUST SILENSER	Not Necessary	1,019.00 FL	*- FL
35	2		*REAR EXHAUST MOUNTING	Not Necessary	100.00 FL	*- FL
36	1		*REAR EXHAUST HEAT PLATE	Not Necessary	415.00 FL	*- FL
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
39	1		*TAILGATE OUTER COVER CLIPS	Necessary	120.00 FS	*30.00 FS
40	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
41	1		*REAR BUMPER UNDER COVER CLIP	Not Necessary	40.00 FS	*- FS
42	1		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*END PANEL TOP TRIM CLIP	Necessary	30.00 FS	*10.00 FS
44	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
45	1		*REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR FENDER INNER TOP TRIM CLIP	Not Necessary	50.00 FS	*- FS
47	1		*REAR FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (\$\$)</b>	<b>31,085.80</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>3,032.58</b>
					<b>Total Parts (\$\$)</b>	<b>28,053.22</b>

**3,342.30**  
**325.23**  
**3,017.07**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	500.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	0.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	0.00
6	REMOVE AND INSTALL TAIL GATE MECHANISM AND PART	New	150.00	0.00
7	REMOVE INSTALL AND CHECK REVERSE CAMERA	New	200.00	50.00
8	REMOVE AND INSTALL CARPET, TRIM AND INTERIOR	New	400.00	0.00
9	REMOVE AND INSTALL REAR EXHAUST	New	150.00	0.00
10	REMOVE INSTALL AND CHECK REVERSE SENSOR	New	200.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,650.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >