

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121010303/UQF3N2**Date:** 25/10/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMY1536D**Insured Vehicle No :** YN183K

Date of Loss: 05/10/2021

Nature of Claim: TP

Claim No: CDMFG21001936

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY1536D**

Make & Model: MERCEDES-BENZ E200 COUPE, 2.0 (R17) (A)

Engine No: 27186030333096

Reg. Date: 21/11/2011 (Man. Year: 2011)

Chassis No: WDD2073482F143207

Colour: Grey

Odometer: 153646 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 ZR18

Rear Tyre Size:

245/40 ZR18

Front Left Side: KAPSEN 6 mm

Rear Left Side:

KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side:

KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,824.24	8,923.71	4,900.53	35.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	2,340.00	1,730.00	42.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,894.24	11,263.71	6,630.53	37.05
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	17,894.24	9,000.00	8,894.24	49.70

INSPECTION

Date of Assignment: 06/10/2021

Date Inspected: 06/10/2021

Inspected At:

Zoom Autowerks Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-53

Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Oct 2021)

Parts: M1-COUPE MERCEDES-BENZ E200 COUPE 2.0 (R17) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY1536D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTRE MOULDING	Distorted	265.00 FL	*255.00 FL
2	2		*REAR BUMPER SIDE BRACKET	Cracked	129.60 FL	*129.60 FL
3	1		*REAR BUMPER }	Distorted	1,670.00 FL	*1,512.32 FL
4	1		*REAR BUMPER TOW GARNISH }		28.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	655.00 FL	*581.00 FL
6	1		*REAR BUMPER CHROME GARNISH CENTRE	Repeated	224.00 FL	*- FL
7	2		*REAR BUMPER CHROME MOULDING SIDES	Necessary	296.00 FL	*296.00 FL
8	2		*REVERSE SENSOR	Shorted	490.00 FL	*450.00 FL
9	1		*REVERSE SENSOR BRACKET (SET)	Not Necessary	96.00 FL	*- FL
10	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
11	1		*BOOTLID PANEL	Dented/Buckled	1,928.00 FL	*1,928.00 FL
12	1		*BOOTLID GARNISH WITH CHROME	Scratched/Cracked	587.00 FL	*481.10 FL
13	1		*BOOTLID INNER LOCK	Twisted	296.00 FL	*296.00 FL
14	1		*BOOTLID EMBLEM E200	Necessary	76.00 FL	*76.00 FL
15	1		*BOOTLID LOGO	Necessary	78.00 FL	*78.00 FL
16	1		*BOOTLID EMBLEM 7G-TRONIC	Necessary	104.00 FL	*92.00 FL
17	1		*BOOTLID EMBLEM C&C	Necessary	48.00 FL	*48.00 FL
18	1		*BOOTLID WEATHER STRIP	Torn	296.00 FL	*296.00 FL
19	1		*BOOTLID THIRD LIGHT	Cracked	896.00 FL	*335.21 FL
20	2		*REAR TAILLAMPS	Cracked	1,412.00 FL	*1,412.00 FL
21	1		*REAR END PANEL	Badly Dented	786.00 FL	*786.00 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	275.00 FL	*275.00 FL
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Warped	428.00 FL	*428.00 FL
25	1		*REAR SPARE TRYE PANEL	Repair	1,180.00 FL	*- FL
26	1		*REAR EXHAUST PIPE	Not Necessary	2,059.00 FL	*- FL
27	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	280.00 FL	*- FL
28	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	195.00 FL	*- FL
29	2		*REAR EXHAUST MOUNTING	Not Necessary	196.00 FL	*- FL
30	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
31	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*REAR NUMBER PLATE W/BASE GARNISH	Bent	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,333.60	9,905.23
- List Item Discount on L Items 10.00/10.00% (\$)	1,509.36	981.52
Total Parts (\$)	13,824.24	8,923.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	950.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	1,100.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	80.00
5	TO REMOVE & INSTALL REAR FENDERS TRIM,GARNISH,SPARE TYRE COMPARTMENT	New	150.00	80.00
6	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	50.00
7	TO RE-PROGRAMME & RE-SET STAR DIAGNOSTICS	New	450.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			4,070.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >