

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21010304/ETY3E2

**Date:** 01/12/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00112752002  
**Claimant Vehicle No :** SLK7463B **Insured Vehicle No :** YN4541J  
Date of Loss: 30/09/2021 Nature of Claim: TP Claim No: SNM21D205605/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK7463B**  
Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: 1NZ9201855  
Reg. Date: 25/01/2017 (Man. Year: 2016) Chassis No: NHP1707060333  
Colour: Red Odometer: 53398 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Rydanz 4 mm Rear Left Side: Rydanz 4 mm  
Front Right Side: Rydanz 4 mm Rear Right Side: Rydanz 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,170.27	7,833.44	7,336.83	48.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,670.00	880.00	24.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,720.27</b>	<b>10,503.44</b>	<b>8,216.83</b>	<b>43.89</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>8,400.00</b>		
<b>(\$\$)</b>	18,720.27	8,400.00	10,320.27	55.13
<b>+ GST 7.00/7.00% (\$\$)</b>	1,310.42	588.00	722.42	55.13
<b>Nett Amount (\$\$)</b>	<b>20,030.69</b>	<b>8,988.00</b>	<b>11,042.69</b>	<b>55.13</b>

### INSPECTION

Date of Assignment: 06/10/2021  
Date Inspected: 07/10/2021 Inspected At: Lion City Rentals Pte Ltd (HQ)  
60 Jalan Lam Huat, #04-35/36 Carros Centre  
Singapore 737569  
Estimated Period of Repair: 8.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2021)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK7463B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L FENDER	Dented	924.00 FL	*654.00 FL
2	1		*F/L FENDER INNER LINER	Missing	234.00 FL	*234.00 FL
3	1		*FRONT HEADLAMP (LH)	Broken	990.00 FL	*990.00 FL
4	1		*FRONT BUMPER	Broken	900.00 FL	*581.00 FL
5	1		*FRONT BUMPER LH PROTECTOR	Missing	238.88 FL	*189.00 FL
6	1		*FRONT BUMPER LH SIDE BRACKET	Missing	90.00 FL	*90.00 FL
7	1		*FRONT BONNET	Dented	1,288.50 FL	*845.00 FL
8	1		*FRONT BONNET HINGE (LH)	Bent	129.00 FL	*129.00 FL
9	1		*F/L DOOR ASSY	Dented	1,610.00 FL	*1,200.00 FL
10	1		*R/L TAILLAMP	Not Necessary	550.00 FL	*- FL
11	1		*R/L TAILGATE REFLECTOR	Not Necessary	380.00 FL	*- FL
12	1		*REAR END PANEL	Not Necessary	828.00 FL	*- FL
13	1		*REAR BUMPER COVER	Dented	900.00 FL	*750.00 FL
14	1		*REAR BUMPER LH SIDE BRACKET	Broken	105.00 FL	*105.00 FL
15	1		*REAR BUMPER LH SEAL	Not Necessary	104.40 FL	*- FL
16	1		*R/L SLIDING DOOR ASSEMBLY	Dented	1,800.00 FL	*1,295.00 FL
17	1		*R/L DOOR OUTER RUBBER PROTECTOR	Missing	280.00 FL	*215.00 FL
18	1		*REAR SLIDING DOOR MOTOR LH	Not Necessary	3,200.00 FL	*- FL
19	1		*R/L FENDER OUTER SIDE GARNISH	Missing	480.00 FL	*128.00 FL
20	1		*R/L FENDER	Repair	924.00 FL	*- FL
21	1		*FRONT BUMPER REINFORCEMENT	Dented	380.00 FL	*380.00 FL
22	1		*FRONT BUMPER ENERGY ABSORBER	Broken	120.00 FL	*120.00 FL
23	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
25	1		*SET FRONT FENDER INNER LINEAR CLIPS	Not Necessary	80.00 FS	*- FS
26	1		*SET REAR REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
27	1		*FRONT GRILLE	Broken	596.25 FL	*596.25 FL
28	1		*FRONT WINDSCREEN	Broken	2,000.00 FL	*1,600.00 FL
29	1		*F/L HEADLAMP PANEL	Bent	175.00 FL	*130.00 FL
30	1		*SET R/L WHEEL CAP	Missing	260.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,977.03</b>	<b>10,391.25</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	4,806.76	2,557.81
<b>Total Parts (\$\$)</b>	<b>15,170.27</b>	<b>7,833.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING OUT F/L FENDER, FRONT HEADLAMP (LH), FRONT BUMPER, F/L AND R/L DOOR AND FRONT BONNET OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,250.00	1,000.00
2	TO RESPRAY F/L FENDER, FRONT BUMPER, FRONT BONNET, FRONT LH TYRE RIM, FRONT LH DOOR AND REAR LH DOOR	New	1,600.00	1,320.00
3	TO APPLY RUSTPROOFING ON ALL REPLACEMENT PARTS	New	100.00	30.00
4	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	200.00
5	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE BATTERY AS A SAFETY PRECAUTIONS	New	300.00	120.00
<b>Gross Labour Cost (\$)</b>			<b>3,550.00</b>	<b>2,670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >