

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010310/UES3Q2
Date: 29/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMC5609S	Insured Vehicle No :	SLX4078G
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5609S		
Make & Model:	KIA CARENS, 2.0 (A)	Engine No:	D4FDJH553267
Reg. Date:	10/07/2018 (Man. Year: 2018)	Chassis No:	KNAHU815VJ7208984
Colour:	Black	Odometer:	261559 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Mozzo 6 mm	Rear Left Side:	Mozzo 6 mm
Front Right Side:	Mozzo 6 mm	Rear Right Side:	Mozzo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,639.00	1,312.20	2,326.80	63.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,260.00	920.00	42.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,819.00	2,572.20	3,246.80	55.80
Approved Total (Overridden) (S\$)		2,050.00		

(S\$)	5,819.00	2,050.00	3,769.00	64.77
+ GST 7.00/7.00% (S\$)	407.33	143.50	263.83	64.77
Nett Amount (S\$)	6,226.33	2,193.50	4,032.83	64.77
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,200.95		

INSPECTION

Date of Assignment: 06/10/2021

Date Inspected: 06/10/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
Parts:	143	KIA CARENS 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC5609S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	676.00 FL	*616.00 FL
2	1		*N/S REAR FENDER	Repair	1,223.00 FL	*- FL
3	1		*N/S REAR FENDER INNER COWLING	Not Necessary	224.00 FL	*- FL
4	8		*N/S REAR FENDER INNER COWLING CLIPS	Not Necessary	40.00 FL	*- FL
5	1		*N/S REAR DOOR	Dented / Bent	842.00 FL	*842.00 FL
6	1		*N/S REAR DOOR PROTECTOR	Not fitted	225.00 FL	*- FL
7	1		*N/S REAR DOOR RUBBER	Not Necessary	125.00 FL	*- FL
8	1		*N/S REAR WHEEL SPORT RIM	Repair	605.00 FL	*- FL
9	1		*N/S REAR FENDER QUARTER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
10	1		*N/S REAR FENDER QUARTER GLASS PRIMER	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,035.00	1,458.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	396.00	145.80
Total Parts (\$\$)	3,639.00	1,312.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT N/S REAR FENDER QUARTER GLASS	New	140.00	0.00
2	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	80.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	30.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	850.00	550.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	950.00	600.00
Gross Labour Cost (\$\$)			2,180.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >