

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010311/EGA3Q2**Date:** 18/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0003651_01

Claimant Vehicle No : SMZ8983U **Insured Vehicle No :** YP6763L

Date of Loss: 04/08/2021 Nature of Claim: TP Claim No: MCV2021D0003781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ8983U**

Make & Model: KIA CERATO, 1.6 LX (A) Engine No: G4FGMH701466

Reg. Date: 25/05/2021 (Man. Year: 2021) Chassis No: KNAF1416MM5105895

Colour: White Odometer: 1287 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35.00	35.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	330.00	270.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	635.00	365.00	270.00	42.52
+ GST 7.00/7.00% (S\$)	44.45	25.55	18.90	42.52
Nett Amount (S\$)	679.45	390.55	288.90	42.52
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		518.00		

INSPECTION

Date of Assignment: 06/10/2021

Date Inspected: 06/10/2021 Inspected At: ETHOZ GROUP LTD (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2022)
Parts:	143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8983U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
2	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
					Sub Total (\$\$)	35.00 35.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	0.00 0.00
					Total Parts (\$\$)	35.00 35.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	300.00	100.00
2	TO RESPRAY AFFECTED AREAS	New	300.00	230.00
Gross Labour Cost (S\$)			600.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >