



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8202L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR RH TAIL LAMP	CRACKED	198.00	198.00
	LESS 25% DISCOUNT		-	-49.50
			198.00	148.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH SIDE GUARD (SAFETY BAR)(SN)	BENT	800.00	800.00
1	REAR RH SIDE GUARD BRACKET (SN)	NOT NECESSARY	200.00	-
1	REAR RH PILLAR OUTER ALUMINIUM PANEL (SN)	BENT	400.00	400.00
1	REAR RH POWERGATE PANEL OUTER (SN)	NOT NECESSARY	380.00	-
1	REAR RH WOODEN PLANK (SN)	CRACKED	600.00	600.00
			2,380.00	1,800.00
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.		600.00	480.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		200.00	100.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	50.00	-
			850.00	580.00
	GRAND TOTAL		3,428.00	2,528.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS/SMO21010312/Uff3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.