

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction



Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) __S + RS __\$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

13/10/21 Bal 6700 with rep 15k.
 1/5/2020 confirmed with Susan
 red: 1428.00; 41%



LIU'S BROTHER AUTO ENGINEERING WORKSHOP
 No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
 ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@gmail.com

Invoice/Ref No: YN8202L190418

Estimate

Customer	
Name: Sompso Insurance Singapore Private Limited	Date: 06-10-21
Address: Motor Claims Department	Vehicle No: YN8202L
50 Raffles Place #05-01 / 06	Model/Make: Mitsubishi
Singapore Land Tower Singapore 048623	Fuso FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Side Guard (Safety Bar) <i>Bent</i>	\$ 800.00	SN ✓
2	Side Guard Bracket <i>1.1</i>	\$ 200.00	SN X
3	Pillar Outer Aluminium Panel <i>Bent</i>	\$ 400.00	SN X
4	Powergate Panel Outer <i>1.1</i>	\$ 380.00	SN X
5	Wooden Plank <i>CNA</i>	\$ 600.00	SN ✓
6	Tail Lamp <i>CNO</i>	\$ 198.00	SN ✓
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	480
	To putty & spray painting & including touch up paint on accident affected areas	\$ 200.00	100
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	17X

Total Parts & Labour of estimate for damaged vehicle \$ 3,428.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*Not Authorised
 when
 7/10/21
 2/5 \$ 2000
 When photo after repair
 3 days*

*1-198
 252
 7-148.50
 S.N-1800
 2-500
 2528.50
 202
 2022*

Liu's Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: