

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3449M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	788.90	788.90
1	FRONT BUPER SIDE RETAINER RH	DAMAGED / NECESSARY	31.00	31.00
1	FRONT BUMPER FOG LAMP COVER RH	REFIX	112.50	-
1	FRONT BUMPER REINFORCEMENT	BENT	405.80	295.00
1	HEADLAMP RH	CRACKED	752.30	752.30
	LESS 25% DISCOUNT		-522.63	-466.80
			1,567.87	1,400.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	150.00	30.00
			150.00	30.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.		360.00	300.00
	TO APPLY UNDERCOATING, PUTTY AND SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		250.00	200.00
	WIRING / BULB CHECKING.		36.00	30.00
			646.00	530.00
<b>GRAND TOTAL</b>			<b>2,363.87</b>	<b>1,960.40</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,550.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS3/LPC21005496/R1vf3e2-1

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.