

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI21010313/KVY3Q2**Date:** 15/11/2021**REFERENCE**Insured/Claimant: HENG BOON SENG CONSTRUCTION PTE LTD  
Date of Loss: 01/10/2021Policy No: DMPCSNW00156592104  
Nature of Claim: OD

Claim No: SNM21D205639/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKU8919G**  
Make & Model: TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)  
Reg. Date: 20/08/2015 (Man. Year: 2015)  
Colour: Metallic Black  
Engine Capacity: 1986 cc  
Market Value/New Car Price: S\$64,000.00  
Sum Insured (S\$): **Market Value/New Car Price**Engine No: 3ZRB589314  
Chassis No: ZSU600049419  
Odometer: 104935 km**CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 8 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 8 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,680.00	3,680.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,580.00	1,050.00	28.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,310.00</b>	<b>6,260.00</b>	<b>1,050.00</b>	<b>14.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00

**Nett Amount (S\$)****6,560.00****4,250.00****2,310.00****35.21**INSPECTION

Date of Assignment: 06/10/2021

Date Inspected: 07/10/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Nexwave Auto (HQ)  
160, Sin Ming Drive, #05-15, Sin Ming Autocity  
Singapore 575722**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKU8919G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	800.00 F	*800.00 F
2	1		*FRONT RIGHT FENDER	Bent	500.00 F	*500.00 F
3	1		*FRONT RIGHT HEADLAMP	Cracked	1,600.00 F	*1,600.00 F
4	1		*FRONT WINDSCREEN	Cracked	780.00 F	*780.00 F
					<b>Total Parts (S\$)</b>	<b>3,680.00</b>
						<b>3,680.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	WINDSCREEN DISMANTLED JOB INSTALLATION (WITH SEALANT)	New	180.00	160.00
2	PANEL BEATING JOB	New	1,000.00	900.00
3	SPRAYWORK	New	1,800.00	1,200.00
4	ROOF PANEL TO DO DISMANTLED JOB	New	500.00	200.00
5	TOWING SERVICES	New	150.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,630.00</b>	<b>2,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >