

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010315/KYA3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900077583
Claimant Vehicle No :	SNA6718C	Insured Vehicle No :	SMJ7414L
Date of Loss:	25/09/2021	Nature of Claim:	TP
		Claim No:	3156954494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA6718C	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ E250, 2.0 (A)	Chassis No:	WDD2073362F311628
Reg. Date:	01/05/2015 (Man. Year: 2015)	Odometer:	117150 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	255/35Z R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,454.97	5,403.58	7,051.39	56.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,640.00	690.00	29.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,784.97	7,043.58	7,741.39	52.36
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	14,784.97	5,500.00	9,284.97	62.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	06/10/2021	
Date Inspected:	06/10/2021 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Bent	3,200.00 FL	*1,985.00 FL
2	1		*REAR FENDER GLASS CHROME (CURVE)	Serviceable	295.00 FL	*- FL
3	1		*REAR FENDER GLASS CHROME (STRAIGHT)	Serviceable	190.00 FL	*- FL
4	1		*REAR FENDER GLASS MOULDING	Necessary	770.00 FL	*281.00 FL
5	1		*REAR FENDER LOWER CHROME PROTECTOR	Necessary	172.00 FL	*172.00 FL
6	1		*REAR BUMPER	Dented / Buckled	1,850.00 FL	*1,512.20 FL
7	9		*REAR BUMPER CLIPS	Necessary	81.00 FL	*81.00 FL
8	1		*REAR BUMPER CORNER RETAINER RH	Serviceable	150.00 FL	*- FL
9	2		*REAR BUMPER CORNER MOULDINGS	Necessary	300.00 FL	*300.00 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
11	7		*REAR WINDSCREEN SIDE SKIRT LOCK CLIPS	Not Necessary	52.50 FL	*- FL
12	1		*REAR WHEEL RIM	Dented / Scratched	1,720.00 FL	*1,300.00 FL
13	2		*REAR WHEEL BEARING	Not Necessary	490.00 FL	*- FL
14	1		*REAR WHEEL UPPER ARM (1)	Serviceable	320.00 FL	*- FL
15	1		*REAR WHEEL UPPER ARM (2)	Serviceable	310.00 FL	*- FL
16	1		*REAR WHEEL TRACK ARM (1)	Serviceable	295.00 FL	*- FL
17	1		*REAR WHEEL TRACK ARM (2)	Serviceable	280.00 FL	*- FL
18	1		*REAR LOWER ARM	Serviceable	330.00 FL	*- FL
19	1		*REAR WHEEL HUB	Serviceable	290.00 FL	*- FL
20	1		*REAR WHEEL KNUCKLE ARM	Serviceable	1,510.00 FL	*- FL
21	2		*REAR KNUCKLE ARM BALL JOINT	Serviceable	110.00 FL	*- FL
22	1		*REAR FENDER GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
23	1		*REAR FENDER GLASS SEALER	Necessary	30.00 FS	*30.00 FS
24	1		*REAR FENDER GLASS FASTENER	Necessary	30.00 FS	*30.00 FS
25	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
26	1		*REAR WINDSCREEN GLASS FASTENER	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,100.50	5,986.20
- List Item Discount on L Items 5.00/10.00% (\$\$)	645.53	582.62
Total Parts (\$\$)	12,454.97	5,403.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REFIT REAR FENDER GLASS	New	80.00	80.00
2	TO DISMANTLE /REFIT FUEL TANK INLET HOSES & PIPING	New	80.00	60.00
3	TO DISMANTLE /REFIT ROOF LINING	New	150.00	120.00
4	TO DISMANTLE /REPLACE REAR UNDER CARRIAGE TO FACILITATE REPAIR	New	160.00	0.00
5	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	0.00
6	TO SUPPLY REAR FENDER BODY SEALANY	New	60.00	30.00
7	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACE /REPAIR PANEL	New	60.00	30.00
8	TO DISMANTLE /REFIT REAR WINDSCREEN GLASS	New	160.00	120.00
9	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FENDER INNER PANEL ,WHEEL HOUSING ETC .CNT ,WELD REAR FENDER PARTS REPLACEMENT	New	900.00	700.00
10	TO RESPRAY AFFECTED AREAS	New	600.00	500.00
Gross Labour Cost (S\$)			2,330.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >