

ASS. REQ. BY:

REF:

AIG/21010351/1ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNA 6718C

Yr Regn:

05.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M A1 E250

c.c

1991

Colour

M Black

A/C:

Insured / Std / NI / NA

Sp. Reading

117150

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2073362F 311628

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

235/40ZR18

R:

235/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/9/21

D.O.I.

6/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Area body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/11/21 8:55 AM Pinned

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
11 Days @ 5500/-
Reserve After Point
6 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **05.10.2021**

Accident Date : **25.09.2021**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mercedes E250 Coupe" Reg. No. SNA6718C Claiming Against Your Insured Reg. No. SMJ7414L			
1pc	Rear Fender RH <i>1P85</i>		<i>As</i> 3200.00 ✓
1pc	Rear Fender Glass Chrome (Curve)		<i>Sn</i> 295.00 X
1pc	Rear Fender Glass Chrome (Straight)		<i>Sn</i> 190.00 X
1pc	Rear Fender Glass Moulding <i>281</i>		<i>Sn</i> 770.00 ✓
1pc	Rear Fender Lower Chrome Protector		<i>Sn</i> 172.00 ✓
1pc	Rear Bumper <i>1512.20</i>		<i>Ref/Bu</i> 1850.00 ✓
9pcs	Rear Bumper Clips	9.00	<i>Sn</i> 81.00 ✓
1pc	Rear Bumper Corner Retainer RH		<i>Sn</i> 150.00 X
2pcs	Rear Bumper Chrome Mouldings	150.00	<i>Sn</i> 300.00 ✓
1pc	Rear Windscreen Moulding		<i>Sn</i> 195.00 ✓
7pcs	Rear Windscreen Side Skirt Lock Clips	7.50	<i>Sn</i> 52.50 X
1pc	Rear Wheel Rim <i>P-1 1300</i>		<i>Ref/Gr</i> 1720.00 ✓
2pcs	Rear Wheel Bearing	245.00	<i>Sn</i> 490.00 X
1pc	Rear Wheel Upper Arm (1)		<i>Sn</i> 320.00 X
1pc	Rear Wheel Upper Arm (2)		<i>Sn</i> 310.00 X
1pc	Rear Wheel Track Arm (1)		<i>Sn</i> 295.00 X
1pc	Rear Wheel Track Arm (2)		<i>Sn</i> 280.00 X
1pc	Rear Lower Arm		<i>Sn</i> 330.00 X
1pc	Rear Wheel Hub		<i>Sn</i> 290.00 X
1pc	Rear Wheel Knuckle Arm		<i>Sn</i> 1510.00 X
2pcs	Rear Knuckle Arm Ball Joints	55.00	<i>Sn</i> 110.00 X
			12,910.50
	Less 5% <i>10%</i>		645.53
			12,264.98
	Rear Fender Glass Sealant		<i>Sn</i> 30.00 SN ✓
	Rear Fender Glass Sealer		<i>Sn</i> 30.00 SN ✓
	Rear Fender Glass Fastener		<i>Sn</i> 30.00 SN ✓
	Rear Windscreen Glass Sealant		<i>Sn</i> 40.00 SN ✓
	Rear Windscreen Glass Fastener		<i>Sn</i> 30.00 SN ✓
	To Dismantle / Refit Rear Fender Glass		80.00 ✓
	To Dismantle / Refit Fuel Tank Inlet Hoses & Piping		80.00 <i>64</i>
	To Dismantle / Refit Roof Lining		150.00 <i>120</i>
		C/F	12,764.98

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **05.10.2021**

Accident Date : 25.09.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mercedes E250 Coupe" Reg. No. SNA6718C Claiming Against Your Insured Reg. No. SMJ7414L		
		B/F	12,764.98
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		<i>nn</i> 160.00 <i>X</i>
	To Conduct Computerize Wheel Alignment Test		<i>nn</i> 80.00 <i>X</i>
	To Supply Rear Fender Body Sealant		<i>3cl</i> 60.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		<i>3cl</i> 60.00
	To Dismantle / Refit Rear Windscreen Glass		<i>12cl</i> 160.00
	Labour Charge - Panel Beating, Repairing of Fender Inner Panel, Wheel Housing etc. Cnt, Weld Rear Fender Parts Replacement		<i>70cl</i> 900.00
	To Respray Affected Areas		<i>50cl</i> 600.00
	Total :		14,784.98

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: