



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Plate Number : SMK747S

Model : Mercedes Benz A200

Damaged Area: (Front LH Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorized
N/A

7/10/21
2/s \$14,800

12 days

Parts / Material :

		Amount
1	Front Bumper	\$ 1,284.00
2	Front Bumper Side Retainer LH <i>DIS</i>	\$ 98.00
3	Front Bumper <i>under cover</i> Torn	\$ 286.00
4	Front Bumper Mount LH <i>^^</i>	\$ 197.00
5	Front Bumper Tow Garnish <i>^^</i>	\$ 78.00
6	Front Bumper Air-Garnish Top LH <i>^^</i>	\$ 108.00
7	Front Bumper Air-Garnish Lower LH <i>7w1</i>	\$ 105.00
8	Front Bumper Angle Sensor <i>nl's shorts</i>	\$ 275.00
9	Front Bumper Sensor Bracket Set <i>^^</i>	\$ 97.00
10	Front Bumper Sponge <i>torn</i>	\$ 286.00
11	Front support panel <i>one</i>	\$ 496.00
12	Front Bumper Badge <i>rel</i>	\$ 118.00
13	Front Bumper Clips <i>rel</i>	\$ 60.00
14	Radiator Grille Assy <i>one</i>	\$ 986.00
15	Front Headlamp Assy LH <i>one</i>	\$ 3,886.00
16	Front Headlamp Bracket LH <i>one</i>	\$ 256.00
17	Bonnet <i>Bent/waged</i>	\$ 1,786.00
18	Floor under cover <i>torn</i>	\$ 328.00
19	Bonnet Insulator Clips <i>^^</i>	\$ 60.00
20	Bonnet Hinge @ SGD\$95.00 <i>see</i>	\$ 190.00
21	Bonnet Actuator @ SGD\$230.00 <i>Activated</i>	\$ 460.00
22	Front Fender LH <i>DIS</i>	\$ 925.00
23	Front Fender Inner Bracket LH <i>Bent</i>	\$ 115.00
24	Front Fender Inner Shield LH <i>torn</i>	\$ 258.00
25	Front Fender Inner Shield Clips <i>rel</i>	\$ 40.00
26	Front Suspension LH <i>Bent</i>	\$ 458.00
27	Front Lower Arm LH <i>Bent</i>	\$ 426.00
28	Front Knuckle Arm LH <i>waged</i>	\$ 1,010.00
29	Front Hub Bearing LH <i>Damaged</i>	\$ 425.00
30	Front Trailing Arm LH <i>Bent</i>	\$ 256.00
31	Front Stabilizer Linkage LH <i>see</i>	\$ 326.00
32	Front Tie Rod LH <i>3w</i>	\$ 180.00
33	Front Tie Rod Outer LH <i>NS</i>	\$ 180.00
34	Crossmember <i>DO/Bent</i>	\$ 2,100.00
35	Wiper Tank <i>torn</i>	\$ 180.00
36	Wiper Pump <i>^^</i>	\$ 110.00
37	Rocker panel garnish <i>nl's</i> Torn	\$ 1,550.00
Parts :		\$ 19,979.00
Less Parts 10% :		\$ 1,997.90
Total Parts :		\$ 17,981.10

3044.61
166.00

392

1866.00

628.00

Special Net Items :

Front Number Plate W/Garnish *n1*
 Front Tire LH *pan*
 Front Sport Rim LH *one*

LP 350 x 80% \$ 80.00 *X*
 \$ 580.00 *280*
 \$ 1,276.00 *900*
Total S/N Parts : \$ 1,936.00

Labour :

To Remove, Repair & Renew Front Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring
 To Re-Position, Drill & Install Angle Sensor
 To Conduct All Wheel Alignment
 To Remove, Renew Rim, Tire & Balance the Same
 To Remove & Renew Front Undercarriage Components to Facilitate Repairs
 To Re-Programme, Reset Star Diagnostic Management
 To Rust Proof Affected Areas

\$ 1,400.00 *900*
 \$ 1,400.00 *1150*
 \$ 50.00 *30*
 \$ 150.00 *50*
 \$ 150.00 *80*
 \$ *11* 100.00 *X*
 \$ 350.00 *✓*
 \$ 450.00 *100*
 \$ 200.00 *60*
Total Labour : \$ 4,250.00

TOTAL PARTS : \$ 17,981.10
TOTAL SPECIAL NET ITEM : \$ 1,936.00
TOTAL LABOUR : \$ 4,250.00
TOTAL REPAIR COST : \$ 24,167.10

DATE OF SURVEY / INSPECTED:
 RECOMMENDED PART BY PART / LUMP SUM :
 RECOMMENDED NUMBER OF DAYS :
 SURVEY BY / SURVEYOR FIRM :
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
 FINALISED AMOUNT :

P- 16323-61
102
P- 14691-24
S.N-1180
L- 2720
18591-24
202
14872

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: