

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010322/APA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700079271
Claimant Vehicle No :	SJV7727G	Insured Vehicle No :	SLS9886J
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	8446673850SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV7727G		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2293034A
Reg. Date:	31/10/2016 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1692146
Colour:	Bronze	Odometer:	66480 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,901.89	26,253.18	23,648.71	47.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	4,430.00	1,920.00	30.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,251.89	30,683.18	25,568.71	45.45
Approved Total (Overridden) (S\$)		24,000.00		
Nett Amount (S\$)	56,251.89	24,000.00	32,251.89	57.33
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		25,207.45		
Global Sum Settlement (S\$)		25,200.00		

INSPECTION

Date of Assignment:	06/10/2021	
Date Inspected:	06/10/2021 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	16.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$60,500.00 (est) less LTA Rebate: \$36,100.00 (est) = Nett Value
:\$24,400.00 (est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	4,344.70 FL	*2,657.00 FL
2	2		*TAILGATE HINGES	Not Necessary	141.80 FL	*- FL
3	1		*TAILGATE UPPER LOCK	Damaged	207.90 FL	*207.90 FL
4	1		*TAILGATE LOWER LOCK	Not Necessary	181.30 FL	*- FL
5	2		*TAILGATE SHOCK ABSORBER	Not Necessary	572.40 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Cut	190.50 FL	*190.50 FL
7	1		*TAILGATE INNER BOARD	Cracked	396.00 FL	*396.00 FL
8	1		*TAILGATE INNER HANDLE	Cracked	78.30 FL	*78.30 FL
9	2		*TAILGATE REFLECTOR	Cracked	706.20 FL	*706.20 FL
10	1		*TAILGATE CENTRE GARNISH	Cracked	403.20 FL	*356.00 FL
11	1		*TAILGATE NISSAN EMBLEM	Necessary	95.90 FL	*95.90 FL
12	1		*TAILGATE QASHQAI EMBLEM	Necessary	116.50 FL	*116.50 FL
13	1		*TAILGATE SIDE MOULDING	Not Necessary	80.00 FL	*- FL
14	1		*REAR TAILGATE INNER TOP GARNISH	Not Necessary	100.80 FL	*- FL
15	2		*REAR NUMBER PLATE LAMP	Not Necessary	214.20 FL	*- FL
16	2		*REAR LAMP	Cracked	777.00 FL	*777.00 FL
17	2		*REAR LAMP HOUSING	Not Necessary	445.20 FL	*- FL
18	1		*REAR BUMPER }	Distorted	956.10 FL	*797.00 FL
19	1		*REAR BUMPER LOWER GARNISH }	Distorted	0.00 FL	*- FL
20	2		*REAR BUMPER SIDE HOLDER	Damaged	122.60 FL	*122.60 FL
21	1		*REAR BUMPER TOWING HOOK COVER	Deformed	33.70 FL	*33.70 FL
22	2		*REAR BUMPER REFLECTOR	Not Necessary	158.60 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Dented	743.10 FL	*619.00 FL
24	1		*REAR BUMPER SPONGE	Cracked	151.70 FL	*151.70 FL
25	2		*REAR BUMPER BRACKET	Distorted	338.80 FL	*338.80 FL
26	1		*REAR END PANEL	Distorted	579.20 FL	*579.20 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	102.00 FL	*102.00 FL
28	1		*REAR SPARE TYRE WELL	Buckled	1,099.80 FL	*1,099.80 FL
29	1		*REAR SPARE TYRE WELL INSULATION (3 PCS)	Necessary	567.54 FS	*200.00 FS
30	1		*REAR SPARE TYRE TOOL SPONGE	Cracked	390.00 FL	*390.00 FL
31	1		*REAR SPARE TYRE TOP BOARD	Deformed	498.20 FL	*498.20 FL
32	2		*REAR TOP BOARD	Not Necessary	383.40 FL	*- FL
33	2		*REAR FENDER INNER SIDE TRIMS	Torn	909.60 FL	*724.00 FL
34	2		*REAR FENDER SIDE GARNISH	Cracked	510.60 FL	*510.60 FL
35	1		*BONNET	Distorted	1,400.90 FL	*1,061.00 FL
36	2		*BONNET HINGES	Not Necessary	109.40 FL	*- FL
37	1		*BONNET LOCK	Damaged	91.90 FL	*91.90 FL
38	1		*BONNET LOCK BRACKET	Not Necessary	74.00 FL	*- FL
39	1		*BONNET SIDE MOULDING	Not Necessary	80.00 FL	*- FL
40	2		*BONNET INNER RUBBER	Not Necessary	215.40 FL	*- FL
41	1		*BONNET INNER COVER	Not Necessary	223.70 FL	*- FL
42	1		*SUPPORT PANEL	Buckled	741.00 FL	*741.00 FL
43	1		*SUPPORT PANEL TOP COVER	Torn	182.50 FL	*182.50 FL
44	1		*SUPPORT PANEL GARNISH	Deformed	90.80 FL	*90.80 FL
45	1		*GRILLE	Cracked	693.20 FL	*498.00 FL
46	1		*GRILLE NISSAN EMBLEM	Necessary	95.90 FL	*95.90 FL
47	2		*HEADLAMP	Cracked	1,616.20 FL	*1,616.20 FL
48	2		*HEADLAMP LOWER GARNISH	Not Necessary	130.00 FL	*- FL
49	1		*BUMPER	Deformed	901.50 FL	*751.00 FL
50	2		*BUMPER SIDE HOLDER	Necessary	84.60 FL	*84.60 FL
51	1		*BUMPER TOWING HOOK COVER	Not Necessary	33.80 FL	*- FL
52	2		*BUMPER FOD LAMP	Not Necessary	777.00 FL	*- FL
53	2		*BUMPER FOD LAMP RIM	Not Necessary	312.40 FL	*- FL
54	1		*BUMPER REINFORCEMENT	Bent	810.50 FL	*588.00 FL
55	1		*BUMPER SPONGE	Cracked	234.90 FL	*234.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*BUMPER BRACKET	Distorted	301.80 FL	*301.80 FL
57	2		*HORN	Cracked	291.40 FL	*291.40 FL
58	1		*HORN BRACKET	Not Necessary	28.00 FL	*- FL
59	1		*OIL COOLER	Dented	2,545.90 FL	*645.00 FL
60	1		*AIR CONDENSER	Dented	836.30 FL	*836.30 FL
61	2		*AIR CONDENSER SIDE GARNISH	Deformed	217.20 FL	*89.00 FL
62	1		*RADIATOR	Bent	859.30 FL	*859.30 FL
63	1		*RADIATOR FAN COWLING }	Damaged	762.30 FL	*762.30 FL
64	1		*RADIATOR FAN MOTOR }	Damaged	0.00 FL	*- FL
65	1		*RADIATOR FAN BLADE}	Damaged	0.00 FL	*- FL
66	1		*RADIATOR TOP HOSE	Not Necessary	74.80 FL	*- FL
67	1		*RADIATOR LOWER HOSE	Not Necessary	61.70 FL	*- FL
68	1		*BUMPER LOWER BEAM	Bent	445.80 FL	*445.80 FL
69	1		*ENGINE LOWER COVER	Torn	370.60 FL	*370.60 FL
70	1		*TUBRO (INTERCOOLER)	Dented	3,074.90 FL	*2,126.00 FL
71	1		*ALTORNATOR	Cracked	1,679.80 FL	*1,679.80 FL
72	1		*AIRCOND COMPRESSOR	Not Necessary	1,268.70 FL	*- FL
73	1		*AIRCOND DISCHARGE HOSE	Not Necessary	232.00 FL	*- FL
74	1		*AIRCOND SUCTION HOSE	Bent	243.60 FL	*243.60 FL
75	1		*AIRCOND LIQUID PIPE	Not Necessary	164.10 FL	*- FL
76	1		*REAR EXHAUST PIPE	Bent	1,145.40 FL	*771.00 FL
77	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	89.80 FL	*- FL
78	1		*REAR EXHAUST PIPE TOP COVER	Crumpled	146.00 FL	*146.00 FL
79	2		*FRONT FENDER SIDE GARNISH	Cracked	510.60 FL	*510.60 FL
80	1		*FRONT RH FENDER	Repair	747.30 FL	*- FL
81	2		*FRONT FENDER INNER SHIELD	Torn	308.00 FL	*308.00 FL
82	1		*ELECTRIC PLATE	Not Necessary	3,120.00 FL	*- FL
83	1		*ELECTRIC BRACKET	Not Necessary	612.40 FL	*- FL
84	1		*TRANSMISSION E.C.U	Not Necessary	1,287.50 FL	*- FL
85	1		*ELECTRIC FAN WIRE	Not Necessary	4,317.40 FL	*- FL
86	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
87	1		*TAILGATE CAMERA	Damaged	500.00 FS	*380.00 FS
88	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
89	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
90	4		*REAR BUMPER REVERSE SENSOR	Damaged	2,880.00 FS	*300.00 FS
91	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
92	1		*SUPPORT PANEL TOP COVER CLIPS (5 PCS)	Necessary	30.00 FS	*20.00 FS
93	1		*NUMBER PLATE	Dented	50.00 FS	*30.00 FS
94	1		*NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	54,969.04	29,050.20
- List Item Discount on L Items 10.00/10.00% (\$)	5,067.15	2,797.02
Total Parts (\$)	49,901.89	26,253.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	100.00	60.00
2	TO SUPPLY REAR END PANEL SEALANT	New	200.00	60.00
3	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
4	TO CHECK WIRING	New	100.00	60.00
5	TO RESET	New	100.00	0.00
6	REMOVE & REINSTALL CAMERA	New	100.00	50.00
7	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	50.00
8	REMOVE & REINSTALL BOOTLID GARNISH	New	200.00	80.00
9	REMOVE & REINSTALL AIRCOND FILL IN GAS	New	200.00	120.00
10	REMOVE & REINSTALL EXHAUST PIPE	New	200.00	0.00
11	REMOVE & REINSTALL OIL COOLER TUBRO	New	200.00	0.00
12	REMOVE & REINSTALL PETROL TANK	New	200.00	0.00
13	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,500.00	2,200.00
14	RESPRAY PAINTING	New	2,000.00	1,700.00
Gross Labour Cost (\$\$)			6,350.00	4,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >