

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21010323/UTF3E2

Date: 03/11/2021

REFERENCE

Insured/Claimant:	DENG HONG	Policy No:	D20MPC0000663-01		
Date of Loss:	06/10/2021	Nature of Claim:	OD	Claim No:	MPC2021D0004306

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2813U	Engine No:	2ZR0A64265
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20WX0J009051
Reg. Date:	05/02/2018 (Man. Year: 2017)	Odometer:	66194 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,371.17	4,922.95	1,448.22	22.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,970.00	1,370.00	41.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,711.17	6,892.95	2,818.22	29.02
Approved Total (Overridden) (S\$)		5,500.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	8,961.17	4,750.00	4,211.17	46.99

INSPECTION

Date of Assignment:	07/10/2021		
Date Inspected:	07/10/2021	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW2813U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	798.80 FL	*798.80 FL
2	1		*FRONT BONNET LOGO EMBLEMS	Necessary	66.20 FL	*66.20 FL
3	1		*FRONT BONNET LOCK	Twisted	92.60 FL	*92.60 FL
4	2		*FRONT BONNET O/S & N/S HINGE	Serviceable	102.20 FL	*- FL
5	6		*FRONT BONNET INSULATOR CLIPS	Not Necessary	24.60 FL	*- FL
6	6		*FRONT BONNET RUBBER CLIPS	Necessary	23.40 FL	*23.40 FL
7	1		*FRONT GRILLE (WITH CHROME MOULDING)	Cracked	472.80 FL	*472.80 FL
8	6		*FRONT GRILLE CLIPS	Necessary	25.20 FL	*25.20 FL
9	1		*FRONT TOP GARNISH COVER	Deformed / Twisted	81.60 FL	*81.60 FL
10	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,179.40 FL	*1,179.40 FL
11	1		*FRONT O/S FENDER	Repair	795.50 FL	*- FL
12	2		*O/S & N/S HEAD LAMP ASSY (HID)	Holder Cracked	2,300.20 FL	*2,300.20 FL
13	1		*FRONT NUMBER PLATE & FRAME	Bent	45.00 FS	*40.00 FS
14	1		*FRONT BUMPER	Deformed / Torn	674.90 FL	*674.90 FL
15	10		*FRONT BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
16	1		*FRONT BUMPER DAMPER	Torn	83.50 FL	*83.50 FL
17	1		*FRONT BUMPER REINFORCEMENT	Bent	295.30 FL	*295.30 FL
18	2		*FRONT BUMPER O/S & N/S SIDE RETAINER	Necessary	110.60 FL	*110.60 FL
19	1		*FRONT BUMPER CENTRE LOWER AIRSCOOP GRILLE	Missing	76.80 FL	*76.80 FL
20	2		*FRONT BUMPER O/S & N/S AIRSCOOP GRILLE	Not Necessary	111.40 FL	*- FL
21	2		*FRONT BUMPER O/S & N/S FOG LAMP ASSY	Not Necessary	740.20 FL	*- FL
22	2		*FRONT BUMPER O/S & N/S FOG LAMP GARNISH	Not Necessary	150.40 FL	*- FL
23	1		*FR CENTRE BRACE PANEL	Bent / Twisted	161.10 FL	*161.10 FL
24	6		*FRONT TOP GARNISH COVER CLIPS	Necessary	25.20 FL	*25.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,479.90	6,550.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,108.73	1,627.65

Total Parts (\$\$)	6,371.17	4,922.95
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	40.00	20.00
2	TO PUTTY & RESPRAY PAINTING (PEARL) ON ALL AFFECTED PARTS	New	1,650.00	850.00
3	TO REMOVE, REFIX & REFILL RA134 GAS, TO ENABLE REPAIR FRONT SUPPORT PANEL & HEAD LAMP PANEL	New	150.00	100.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL, FRONT O/S FENDER & NECESSARY PARTS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,340.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >