

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010325/EVY3N2**Date:** 15/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00061472102

**Claimant Vehicle
No :** SLE9219J**Insured Vehicle
No :** GBB9101Z

Date of Loss: 02/10/2021

Nature of Claim: TP

Claim
No: SNM21D205687/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLE9219J**

Make & Model: TOYOTA AXIO, 1.5 (A)

Engine No: 1NZR360315

Reg. Date: 05/08/2016 (Man. Year: 2016)

Chassis No: NKE1657129130

Colour: Silver

Odometer: 252485 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size:

185/60R15

Front Left Side: Firenza 5 mm

Rear Left Side:

Firenza 5 mm

Front Right Side: Firenza 5 mm

Rear Right Side:

Firenza 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,135.00	863.75	2,271.25	72.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	420.00	1,780.00	80.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,335.00	1,283.75	4,051.25	75.94
Approved Total (Overridden) (\$\$)		1,050.00		
(\$\$)	5,335.00	1,050.00	4,285.00	80.32
+ GST 7.00/7.00% (\$\$)	373.45	73.50	299.95	80.32
Nett Amount (\$\$)	5,708.45	1,123.50	4,584.95	80.32

INSPECTION

Date of Assignment: 07/10/2021

Date Inspected: 07/10/2021 Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros Centre
Singapore 737569

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2021)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE9219J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT WEATHERSTRIP	Not Necessary	270.00 FL	*- FL
2	1		*REAR END PANEL TOP COVER/GARNISH	Not Necessary	342.00 FL	*- FL
3	1		*REAR END PANEL	Not Necessary	792.00 FL	*- FL
4	1		*REAR BUMPER	Dented	912.00 FL	*780.00 FL
5	1		*REAR BUMPER LH SIDE RETAINER	Broken	138.00 FL	*65.00 FL
6	1		*REAR BUMPER LH SIDE ARM	Not Necessary	56.00 FL	*- FL
7	1		*REAR BUMPER LH REFLECTOR	Not Necessary	100.00 FL	*- FL
8	1		*R/L TAILLAMP	Not Necessary	850.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
10	1		*SET BODY SEALANT	Not Necessary	200.00 FS	*- FS
11	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,000.00	1,075.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	865.00	211.25
Total Parts (\$\$)	3,135.00	863.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER,REAR END PANEL INNER AND OUTER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	800.00	200.00
2	TO RESPRAY REAR BUMPER,END PANEL INNER AND OUTER PANEL,SPARE TYRE PANEL	New	800.00	220.00
3	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE BATTERY AS A SAFETY PRECAUTIONS	New	300.00	0.00
4	TO CONDUCT STANDARD OF OPERATING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TESTS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
Gross Labour Cost (\$)			2,200.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >