10/29/21, 10:11 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010327/EUF3N2

Date: 29/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210054887

Claimant Vehicle FBK835B Insured Vehicle No: YQ1024P

Date of Loss: 04/10/2021 Nature of Claim: TP Claim No: 3440279686SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK835B

Make & Model: YAMAHA MTM850A (XSR900), 847cc Engine No: N701E089597

Reg. Date: 02/02/2018 (Man. Year: 2017) Chassis No: JYARN431000008872

Colour: Black Odometer: 25418 km

Engine Capacity: 847 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70ZR17 Rear Tyre Size: 180/55ZR17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment: 07/10/2021

Dynasty Motor Pte Ltd (HQ)

50 Bukit Batok Street 23, #01-24 Midview Building

Singapore 659578

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: Tan Hui Zhen

07/10/2021 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$18,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
2	1		*FRONT FORK ASSY	Bent	0.00 F	*-F
3	1		*FRONT FORK BRACKET	*Check	0.00 F	*-F
4	1		*HANDLE BAR	Bent	0.00 F	*-F
5	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*-F
6	1		*CLUTCH LEVER	Cut	0.00 F	*- F
7	1		*ENGINE GUARD MOUNTING	Cut	0.00 F	*- F
8	1		*CLUTCH ENGINE COVER	Cut	0.00 F	*-F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00
			Report was unsubmitted d	uring this print-out.		

10/29/21, 10:11 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >