

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21010328/GQY3E2**Date:** 11/04/2022**REFERENCE**

Insured/Claimant:	SURESH MINHAS	Policy No:	7210020626	
Date of Loss:	06/10/2021	Nature of Claim:	OD	Claim No: 1768799735SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMY3307K</b>		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC23753
Reg. Date:	26/02/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF34M1063389
Colour:	Blue	Odometer:	12897 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$156,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,651.40	13,454.56	11,196.84	45.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,984.00	6,594.00	7,390.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>38,635.40</b>	<b>20,048.56</b>	<b>18,586.84</b>	<b>48.11</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	37,835.40	19,248.56	18,586.84	49.13
<b>+ GST 7.00/7.00% (S\$)</b>	2,648.48	1,347.40	1,301.08	49.13
<b>Nett Amount (S\$)</b>	<b>40,483.88</b>	<b>20,595.96</b>	<b>19,887.92</b>	<b>49.13</b>

**INSPECTION**

Date of Assignment:	07/10/2021		
Date Inspected:	06/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	217.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - RH	Not Necessary	110.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	383.00 FS	*306.40 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	153.00 FS	*122.00 FS
8	1		*RADIATOR GRILLE	Not Necessary	1,433.00 FS	*- FS
9	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	243.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Deformed	39.00 FS	*30.48 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Cut	123.00 FS	*98.00 FS
15	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
16	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
17	1		*SIGNAL HORN	Not Necessary	130.00 FS	*- FS
18	1		*HORN BRACKET - RH	Not Necessary	22.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
20	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*FRONT FENDER - RH	Buckled	1,286.00 FS	*1,028.80 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
23	1		*FRONT FENDER BRACE - RH	Bent	88.00 FS	*69.76 FS
24	1		*FRONT FENDER BRACKET - RH	Bent	32.00 FS	*24.88 FS
25	1		*HEADLIGHT MOUNTING - RH	Broken	118.00 FS	*94.40 FS
26	1		*LED HEADLIGHT - RH	Cut	5,589.00 FS	*4,471.20 FS
27	1		*LIFT CYLINDER - RH	Not Necessary	210.00 FS	*- FS
28	1		*HEADLIGHT HOSE - RH	Not Necessary	80.00 FS	*- FS
29	2		*FRONT WHEEL ARCH COVER - LH / RH	Cut	536.00 FS	*428.80 FS
30	1		*LOCK CARRIER	Not Necessary	1,272.00 FS	*- FS
31	6		*RADIATOR COOLANT	Not Necessary	267.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE - RH	Not Necessary	38.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	42.00 FS	*- FS
34	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	7.00 FS	*- FS
35	1		*FRONT ALUMINIUM RIM - RH	Cut	1,262.00 FS	*1,009.60 FS
36	1		*FRONT LOWER ARM - RH	Bent	454.00 FS	*362.80 FS
37	1		*FRONT WHEEL HUB WITH BEARING - RH	Damaged	528.00 FS	*434.80 FS
38	1		*FRONT WHEEL BEARING HOUSING - RH	Damaged	668.00 FS	*534.00 FS
39	1		*FRONT LOWER ARM BALL JOINT - RH	Bent	140.00 FS	*111.60 FS
40	1		*FRONT COUPLING ROD - RH	Not Necessary	93.00 FS	*- FS
41	1		*GAS SHOCK ABSORBER - RH	Bent	306.00 FS	*244.40 FS
42	1		*TIE ROD - RH	Bent	87.00 FS	*69.28 FS
43	1		*TIE ROD END - RH	Bent	122.00 FS	*97.20 FS
44	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
45	1		*SUNDRIES	Necessary	400.00 FS	*131.44 FS
46	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	304.40 FS	*304.40 FS
			(Supplementary)			
47	1		*FRONT WHEEL HOUSING LINER CAP - RH	Missing	16.00 FS	*12.24 FS
			(Supplementary)			
48	1		*STEERING GEAR REPAIR SET	Necessary	46.00 FS	*36.16 FS
			(Supplementary)			
49	1		*STEERING GEAR	Bent	5,182.00 FS	*2,572.80 FS
			(Supplementary)			
50	1		*STEERING GEAR CLAMP KIT	Necessary	46.00 FS	*36.16 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>24,651.40</b>
						<b>13,454.56</b>
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	400.00
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (R1234)	New	2,000.00	0.00
4	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUB FRANE. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	3,000.00	1,650.00
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT TEST	New	520.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
<b>Gross Labour Cost (\$)</b>			<b>13,984.00</b>	<b>6,594.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >