

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS4/MSG21010329/GVF3E2**Date:** 24/03/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001744264		
Claimant Vehicle No :	YP9299R	Insured Vehicle No :	XD7044Y		
Date of Loss:	02/10/2021	Nature of Claim:	TP	Claim No:	263525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP9299R	Engine No:	6M60241645
Make & Model:	MITSUBISHI FK61FM, 7.5 D (M)	Chassis No:	FK62FMA40023
Reg. Date:	01/08/2018 (Man. Year: 2018)	Odometer:	77003 km
Colour:	White		
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/70 R19.5	Rear Tyre Size:	265/70 R19.5 (D)
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6/6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	1,300.00	1,300.00	0.00	0.00
Labour	4,800.00	0.00	4,800.00	100.00
Paintwork Labour	1,500.00	0.00	1,500.00	100.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,600.00	1,300.00	6,300.00	82.89
+ GST 7.00/7.00% (S\$)	532.00	91.00	441.00	82.89
Nett Amount (S\$)	8,132.00	1,391.00	6,741.00	82.89

INSPECTION

Date of Assignment:	07/10/2021	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	25/10/2021	Inspected At:	Kan Fook Sing Motor Workshop (Defu)
			No. 61 Defu Lane 12
			Singapore 539147
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$6,300.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Mar 2022)	
Parts:	N/A	MITSUBISHI FK61FM 7.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP9299R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SIDE PANEL LOGO RH (Scratched)	1,300.00	1,300.00
Sub Total (\$\$)			1,300.00	1,300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES (* Check)	New	1,500.00	0.00
Labour Items				
2	TO REMOVE ALL NECESSARY AFFECTED PARTS, TO SUPPLY MATERIALS AND FABRICATE SIDE PANEL RH (* Check)	New	4,800.00	0.00
Gross Labour Cost (\$\$)			6,300.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >