

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010333/KVY3N2**Date:** 21/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00110662100	
Claimant Vehicle No :	SMM798J	Insured Vehicle No :	YQ2471A	
Date of Loss:	05/10/2021	Nature of Claim:	TP	Claim No: SNM21D205705/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM798J		Engine No:	1NZX632223
Make & Model:	TOYOTA VIOS, 1.5 E (A)		Chassis No:	MR053HY9305030589
Reg. Date:	10/10/2007 (Man. Year: 2007)		Odometer:	433071 km
Colour:	Silver			
Engine Capacity:	1497 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,079.00	691.20	387.80	35.94
Miscellaneous Items	200.00	200.00	0.00	0.00
Labour	1,330.00	1,130.00	200.00	15.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,609.00	2,021.20	587.80	22.53
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,609.00	2,000.00	609.00	23.34
+ GST 7.00/7.00% (S\$)	182.63	140.00	42.63	23.34
Nett Amount (S\$)	2,791.63	2,140.00	651.63	23.34

INSPECTION

Date of Assignment:	12/10/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	07/10/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM798J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled/Cracked	165.00 F	*165.00 FL
2	1		*1 PC REAR BUMPER LH REFLECTOR	Serviceable	35.00 F	*- FL
3	1		*1 PC REAR BUMPER LH SIDE RETAINER	Distorted	35.00 F	*35.00 FL
4	1		*6 PCS REAR BUMPER CLIPS @1.5/PC	Necessary	9.00 F	*9.00 FL
5	1		*1 PC REAR BOOT	Bent	320.00 F	*320.00 FL
6	1		*1 PC REAR BOOT LOGO	Necessary	30.00 F	*30.00 FL
7	1		*1 PC REAR BOOT EMBLEM (VIOS)	Necessary	35.00 F	*35.00 FL
8	1		*1 PC REAR BOOT OUTER GARNISH	Warped	75.00 F	*75.00 FL
9	1		*1 PC REAR BOOT INNER LOCK	Repair	40.00 F	*- FL
10	1		*1 PC REAR BOOT INNER RUBBER	Serviceable	45.00 F	*- FL
11	1		*1 PC LH TAILLAMP	Serviceable	95.00 F	*- FL
12	1		*1 PC REAR CENTRE PANEL	Bent	195.00 F	*195.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,079.00	864.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	172.80
Total Parts (\$\$)	1,079.00	691.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 SET REVERSE SENSOR (Shorted)	200.00	200.00
Sub Total (\$\$)			200.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	500.00
2	PUTTY & RESPRAY ON REAR BUMPER,BOOT,REAR PANEL,REAR LH FENDER	New	700.00	600.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,330.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >