

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010334/BTY3N2**Date:** 12/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00032292100		
Claimant Vehicle No :	SGZ9864U	Insured Vehicle No :	SKB7527K		
Date of Loss:	05/10/2021	Nature of Claim:	TP	Claim No:	SNM21D205688/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ9864U	Engine No:	3SZ1956980
Make & Model:	TOYOTA RUSH, 1.5 (A)	Chassis No:	J200E0017772
Reg. Date:	26/11/2007 (Man. Year: 2007)	Odometer:	270004 km
Colour:	Silver		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,496.90	3,836.67	3,660.23	48.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,360.00	1,520.00	52.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,376.90	5,196.67	5,180.23	49.92
Approved Total (Overridden) (\$\$)		4,150.00		
(\$\$)	10,376.90	4,150.00	6,226.90	60.01
+ GST 7.00/7.00% (\$\$)	726.38	290.50	435.88	60.01
Nett Amount (\$\$)	11,103.28	4,440.50	6,662.78	60.01

INSPECTION

Date of Assignment:	11/10/2021	
Date Inspected:	07/10/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2021)
Parts:	M1-SUV	TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ9864U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	945.60 FL	*945.60 FL
2	1		*TAILGATE RUSH EMBLEM	Necessary	104.44 FL	*79.80 FL
3	1		*TAILGATE SPARE TRYE OUTER COVER	Broken	1,539.90 FL	*865.40 FL
4	1		*TAILGATE SPARE TRYE INNER COVER	Not Damaged	355.50 FL	*- FL
5	1		*TAILGATE SPARE TRYE BRACKET	Not Damaged	286.80 FL	*- FL
6	1		*TAILGATE LOCK	Not Damaged	145.90 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Broken	769.80 FL	*769.80 FL
8	1		*TAILGATE WEATHERSTRIP	Not Damaged	316.60 FL	*- FL
9	1		*TAILGATE ABSORBER STAY	Not Damaged	98.80 FL	*- FL
10	1		*REAR BUMPER	Dented	987.60 FL	*780.30 FL
11	1		*REAR BUMPER RH SIDE RETAINER	Necessary	42.70 FL	*42.70 FL
12	1		*REAR BUMPER LH SIDE RETAINER	Necessary	42.70 FL	*42.70 FL
13	1		*REAR BUMPER RH REFLECTOR	Not Damaged	50.80 FL	*- FL
14	1		*REAR BUMPER LH REFLECTOR	Not Damaged	50.80 FL	*- FL
15	1		*REAR BUMPER TOWING COVER	Not Damaged	28.20 FL	*- FL
16	1		*REAR BUMPER RH NUMBER PLATE LAMP	Missing	52.50 FL	*52.50 FL
17	1		*REAR BUMPER LH NUMBER PLATE LAMP	Broken	52.50 FL	*52.50 FL
18	1		*RH TAILLAMP ASSY	Broken	556.90 FL	*365.10 FL
19	1		*LH TAILLAMP ASSY	Broken	556.90 FL	*365.10 FL
20	1		*END PANEL (OUTER)	Dented	313.70 FL	*287.40 FL
21	1		*END PANEL (INNER)	Not Damaged	513.60 FL	*- FL
22	1		*END PANEL INNER GARNISH	Not Damaged	83.10 FL	*- FL
23	1		*EXHAUST SILENCER	Not Damaged	708.50 FL	*- FL
24	1		*REAR RH FENDER INNER TRIM BOARD	Not Damaged	458.70 FL	*- FL
25	1		*TAILGATE RH ARTWORK STICKER	Necessary	35.00 FS	*20.00 FS
26	1		*TAILGATE LH ARTWORK STICKER	Necessary	65.00 FS	*40.00 FS
27	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
28	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	No such part	50.00 FS	*- FS
29	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
32	1		*REAR BUMPER RH ARTWORK STICKER	Repeated	35.00 FS	*- FS
33	1		*REAR BUMPER LH ARTWORK STICKER	Repeated	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,762.54	4,998.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,265.64	1,162.23
Total Parts (\$\$)	7,496.90	3,836.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	60.00	0.00
5	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	200.00	80.00
6	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	100.00	60.00
8	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	240.00	0.00
Gross Labour Cost (\$\$)			2,880.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >