

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010335/KES3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210032741
Claimant Vehicle No :	SJG8753C	Insured Vehicle No :	EH95A
Date of Loss:	05/10/2021	Nature of Claim:	TP
		Claim No:	3894772612SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG8753C	Engine No:	4G18JR0793
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U007702
Reg. Date:	18/07/2008 (Man. Year: 2008)	Odometer:	120019 km
Colour:	Metallic Grey		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Maxxis 9 mm	Rear Left Side:	Maxxis 8 mm
Front Right Side:	Maxxis 9 mm	Rear Right Side:	Maxxis 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,700.00	1,042.40	657.60	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	720.00	580.00	44.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,000.00	1,762.40	1,237.60	41.25
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	3,000.00	1,400.00	1,600.00	53.33
+ GST 7.00/7.00% (S\$)	210.00	98.00	112.00	53.33
Nett Amount (S\$)	3,210.00	1,498.00	1,712.00	53.33
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,680.00		

INSPECTION

Date of Assignment:	07/10/2021	Ah Lim Motor Company (AMK)
Date Inspected:	08/10/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILAMP LH	Cracked	421.00 FL	*421.00 FL
2	1		*TAILAMP GROMMET INNER LH	Necessary	5.00 FL	*5.00 FL
3	1		*TAILAMP GROMMET OUTER LH	Necessary	5.00 FL	*5.00 FL
4	1		*TAILAMP PANEL LH	Repair	62.00 FL	*- FL
5	1		*REAR BUMPER	Buckled	697.00 FL	*697.00 FL
6	1		*REAR BUMPER SIDE RETAINER LH	Bent	50.00 FL	*50.00 FL
7	5		*REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
8	18		*REAR BUMPER RIVET	Necessary	90.00 FL	*90.00 FL
9	2		*REAR BUMPER GROMMET	Necessary	10.00 FL	*10.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	209.00 FL	*- FL
11	1		*REAR SPLASH SHIELD LH	Serviceable	28.00 FL	*- FL
12	1		*REAR END PANEL	Repair	495.00 FL	*- FL
13	1		*REAR AIR VENT LH	Serviceable	28.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	2,125.00	1,303.00
- List Item Discount on L Items 20.00/20.00% (\$\$)		425.00	260.60
	Total Parts (\$\$)	1,700.00	1,042.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC ,TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD REAR END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL ,REAR FENDER LH,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	300.00
4	TO SPRAY REAR BUMPER ,REAR FENDER LH ,REAR END PANEL	New	600.00	400.00
Gross Labour Cost (\$)			1,300.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >