



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1522T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LHF DOOR	DENTED	2,824.89	2,350.00
1	LHF DOOR WEATHER SEAL	NECESSARY	305.97	290.00
1	LHF DOOR LOCK	SERVICEABLE	573.12	-
1	LHF DOOR GLASS REGULATOR	SERVICEABLE	355.67	-
1	LHR DOOR	TO REPAIR SEE LABOUR	2,683.97	-
1	LHR DOOR WEATHER SEAL	SERVICEABLE	305.97	-
1	LH STEP PANEL	DENTED / GRAZED	1,462.50	1,150.00
	LESS 10% DISCOUNT		-	-379.00
			8,512.09	3,411.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & TRANSFER LHF COMPONENTS.		250.00	60.00
	TO CHECK LIGHTINGS & WIRINGS.	NOT NECESSARY	50.00	-
	TO RENEW ALL DAMAGED PARTS. REFORM, REPAIR & RE-ALIGN ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF LHR DOOR.		750.00	400.00
	TO RESPRAY ALL AFFECTED AREAS.		1,000.00	500.00
			2,050.00	960.00
	<b>GRAND TOTAL</b>		<b>10,562.09</b>	<b>4,371.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,371.00</b>

Report Ref No. CS3/AIG21009487/Gtf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.