



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Ref: CS3/AIG21009487/Gtf3e2-1 Date: 26/10/2021  Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLU 5988P	Veh. Inspected	SLM 1522T
Policy No.	1700086735	Coverage (\$)	0.00
Claim No.	4970743135SG	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	07/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ GLC250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDC2533462F439846	Colour	BLACK
Odometer	34709 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/50 R19	BRIDGESTONE	6 mm
L/H Front Tyre	235/50 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	235/50 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	235/50 R19	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	02/09/2021	Inspection Date	09/09/2021
Survey held at	160 SIN MING DRIVE #06-13 SIN MING		
Repairer	Y2K AUDIO DESIGN		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	