

ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Yeo Meng Kwee
C/o: 160 Sin Ming Drive #06-13
Sin Ming AutoCity (S) 575722

Date of report: 30.09.2021
Date of request: 09.09.2021
Date of inspection: 09.09.2021
Date of accident: 02.09.2021
Claim type: Third Party Claim

Report No: AAS/2021/200

Particulars of affected vehicle:

Registration no: SLM1522T
Make/Model: Mercedes Benz GLC250 (A)
Year of registration: 2018/19
Colour: Metallic Black

Odometer: 34709 km
Engine Capacity: 1991 cc
Engine no: 27492031443237
Chassis no: WDC2533462F439846

Condition of tires:

Front Left: 7mm
Make: Bridgestone
Rear Left: 7mm
Make: Bridgestone

Front Right: 7mm
Make: Bridgestone
Rear Right: 7mm
Make: Bridgestone

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conducted at M/s. Y2K Audio Design
160 Sin Ming Drive #06-13
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)


Assessment

Repairer's estimate: \$ 10,562.09

Revised estimate: \$ 5,823.36

Recommended reserve: \$ 5,823.36 (Part by Part)

Estimated normal duration of repairs : 5 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SLM1522T

Report No: AAS/2021/200

W/O PREJUDICE

Point of impact

At the LHS portion.

General description of damages

The LHF door, LHR door, LH stet panel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Y2K Audio Design as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,823.36

Conclusion

The repairer has agreed to undertake the repair on a Part by Part basics of SGD \$5,823.36


Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 5 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 46 photographs.

Your Faithfully

Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9688-0413 Fax: 6266-7396
 Email: absolute.app.svcs@gmail.com

Vehicle No: SLM1522T

Report No: AAS/2021/200

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	LHF door ✓	1	Dented	2350	\$ 2,824.89	\$ 2,824.89
2	LHF door weather seal ✓	1	Necessary	290	\$ 305.97	\$ 305.97
3	LHF door lock SVC	1	Refit		\$ 573.12	-
4	LHF door glass regulator SVC	1	Refit		\$ 355.67	-
5	LHR door REPAIR	1	Dented/Repair		\$ 2,683.97	-
6	LHR door weather seal SVC	1	Not Necessary		\$ 305.97	-
7	LH step panel ✓	1	Dented/Grazed	1150	\$ 1,462.50	\$ 1,462.50
				3790		
				-10%: 3411		
				Total:	\$ 8,512.09	\$ 4,593.36

S/N	Labour Description	Repairer's Est	Revised Est
1	To remove & transfer LHF components.	\$ 250.00	\$ 100.00 60
2	To check lightings & wirings.	\$ 50.00	\$ 30.00 X
3	To renew all damaged parts. Reform, repair & re-align all affected area.	\$ 750.00	\$ 500.00 400
4	To respray all affected areas.	\$ 1,000.00	\$ 600.00 500
		Labour Total:	\$ 2,050.00
			\$ 1,230.00

Grand Total: \$ 10,562.09 \$ 5,823.36

The final adjusted Part by Part amount is \$5,823.36

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

4371
4 days

46 Photographs were taken at the time of inspection.

