

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010336/VEA3Q2**Date:** 05/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800102536
<b>Claimant Vehicle No :</b>	FBR3923Z	<b>Insured Vehicle No :</b>	FBL2423M
Date of Loss:	04/10/2021	Nature of Claim:	TP
		Claim No:	1439009280SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBR3923Z</b>	Engine No:	G3K5E0152761
Make & Model:	YAMAHA R15, 155cc ABS	Chassis No:	ME1RG525BK0061101
Reg. Date:	28/05/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	110-70 R17	Rear Tyre Size:	110-70 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,410.80	3,338.30	6,072.50	64.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	350.00	1,710.00	83.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,470.80</b>	<b>3,688.30</b>	<b>7,782.50</b>	<b>67.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,470.80</b>	<b>2,950.00</b>	<b>8,520.80</b>	<b>74.28</b>
<b>+ Loss of Use (5.0 x S\$30.00/day) (S\$)</b>		150.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>3,136.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,130.00</b>		

**INSPECTION**

Date of Assignment:	07/10/2021	
Date Inspected:	07/10/2021	Inspected At: KARZ WORKS PTE LTD 53 Ubi Avenue 1 #01-23, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST SILENCER	Scratched	600.00 FL	*50.00 FL
2	2		*EXHAUST SILENCER COVER	Scratched	200.00 FL	*85.00 FL
3	1		*PILLION FOOTREST	Scratched	90.00 FL	*60.00 FL
4	1		*DRIVER FOOTREST	Scratched	90.00 FL	*35.00 FL
5	1		*DRIVER FOOTREST BRACKET	Serviceable	120.00 FL	*- FL
6	1		*BRAKE PEDAL	Scratched	90.00 FL	*55.00 FL
7	1		*FRONT HEADLAMP	Cracked	400.00 FL	*185.00 FL
8	1		*FRONT HEADLAMP BRACKET	Scratched	12.00 FL	*12.00 FL
9	1		*FRONT HEADLAMP FAIRING OUTER	Cut	350.00 FL	*250.00 FL
10	1		*FRONT HEADLAMP FAIRING INNER	Cut	350.00 FL	*150.00 FL
11	2		*FRONT FAIRING SMALL LH/RH	Cut	240.00 FL	*80.00 FL
12	1		*WHEEL SHAFT	Serviceable	250.00 FL	*- FL
13	1		*AIR INTAKE COVER	N/S Bent	280.00 FL	*60.00 FL
14	1		*SET BALANCER	Missing	150.00 FL	*60.00 FL
15	1		*HANDLEBAR	Bent	280.00 FL	*85.00 FL
16	1		*SET FRONT FORK	Bent	650.00 FL	*450.00 FL
17	1		*FRONT FORK BRACKET (LOWER)	Bent	180.00 FL	*180.00 FL
18	1		*FRONT FENDER	Serviceable	250.00 FL	*- FL
19	1		*LH FAIRING INNER /OUTER	Outer Scratched	700.00 FL	*200.00 FL
20	1		*RH FAIRING INNER /OUTER	Outer Scratched	700.00 FL	*200.00 FL
21	1		*LH MIDDLE FAIRING	Serviceable	200.00 FL	*- FL
22	1		*RH MIDDLE FAIRING	Serviceable	200.00 FL	*- FL
23	1		*LH LOWER FAIRING	Scratched	200.00 FL	*80.00 FL
24	1		*RH LOWER FAIRING	Scratched	200.00 FL	*80.00 FL
25	1		*METER	Not Necessary	300.00 FL	*- FL
26	1		*BRAKE PUMP	Repair	500.00 FL	*- FL
27	1		*FUEL TANK (CENTRE)	Repair	350.00 FL	*- FL
28	1		*FUEL TANK FAIRING (SIDE)	Distorted	280.00 FL	*280.00 FL
29	1		*WINDSHIELD (AFTER MARKET)	Distorted	300.00 FS	*130.00 FS
30	1		*WINDMIRROR (AFTER MARKET)	N/S Serviceable /O/S Scratched	280.00 FS	*150.00 FS
31	1		*BRAKE LEVER (AFTER MARKET)	Scratched	150.00 FS	*30.00 FS
32	1		*CLUTCH LEVER (AFTER MARKET)	Scratched	150.00 FS	*30.00 FS
33	1		*SET SIGNAL LAMP (AFTER MARKET)	Cracked / Missing	180.00 FS	*100.00 FS
34	1		*FRONT SPORT RIM	Dent	300.00 FS	*300.00 FS
35	1		*FORK OIL	Not Necessary	20.00 FS	*- FS
36	1		*FORK SEAL	Not Necessary	20.00 FS	*- FS
37	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
38	1		*RADIATOR	Scratched	600.00 FL	*250.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,292.00</b>	<b>3,627.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	881.20	288.70
<b>Total Parts (\$)</b>	<b>9,410.80</b>	<b>3,338.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	60.00	20.00
2	TO REMOVE AND REPLACE EXHAUST SILENCER	New	200.00	30.00
3	TO R&R SUSPENSION ,HANDLE BAR ,HEADLAMP & FAIRING	New	600.00	200.00
4	TO SPRAY FENDER ,FAIRING AND AFFECTED AREAS	New	1,000.00	100.00
5	TO CHECK WIRING SYSTEM	New	200.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>2,060.00</b>
				<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >