



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 6206E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR LH (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR WINDOW MOULDING LH (CONSISTENT)	NOT NECESSARY	145.00	-
1	FRONT DOOR INNER WINDOW MOULDING LH (CONSISTENT)	NOT NECESSARY	156.00	-
1	FRONT DOOR OUTER GARNISH LH (CONSISTENT)	SCRATCHED	404.00	380.00
1	FRONT DOOR LOCK LH (CONSISTENT)	NOT NECESSARY	325.00	-
1	FRONT DOOR LOCK CATCH LH (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT DOOR WEATHERSTRIP LH (CONSISTENT)	NOT NECESSARY	297.00	-
1	FRONT DOOR INNER WEATHERSTRIP LH (CONSISTENT)	NOT NECESSARY	311.00	-
1	REAR DOOR LH (CONSISTENT)	BENT	1,371.00	1,255.00
1	REAR DOOR WINDOW MOULDING LH (CONSISTENT)	NOT NECESSARY	123.00	-
1	REAR DOOR INNER WINDOW MOULDING LH (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR DOOR OUTER GARNISH LH (CONSISTENT)	MISSING	456.00	332.00
1	REAR DOOR LOCK LH (CONSISTENT)	NOT NECESSARY	317.00	-
1	REAR DOOR LOCK CATCH LH (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR DOOR INNER BOARD LH (CONSISTENT)	NOT NECESSARY	543.00	-
1	REAR DOOR POWER WINDOW MOTOR LH (CONSISTENT)	NOT NECESSARY	409.00	-
1	REAR DOOR WINDOW REGULATOR LH (CONSISTENT)	NOT NECESSARY	278.00	-
2	REAR DOOR HINGE LH @\$62.00(CONSISTENT)	NOT NECESSARY	124.00	-
1	REAR DOOR WEATHERSTRIP LH (CONSISTENT)	NECESSARY	295.00	175.00
1	REAR DOOR INNER WEATHERSTRIP LH (CONSISTENT)	NOT NECESSARY	306.00	-
1	ROCKER PANEL LH (CONSISTENT)	BENT	917.00	546.00
1	SIDE SKIRT LH (CONSISTENT)	SCRATCHED	994.00	541.00
1	REAR WINDSCREEN MOULDING (NPA)(CONSISTENT)	NOT NECESSARY	-	-
1	REAR FENDER LH (NPA)(CONSISTENT)	NOT NECESSARY	-	-
1	REAR FENDER COWLING LH (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR WHEEL ARC PROTECTOR LH (CONSISTENT)	SCRATCHED	379.00	237.00
1	TAIL LAMP LH (CONSISTENT)	NOT NECESSARY	478.00	-
1	REAR BUMPER (CONSISTENT)	NOT NECESSARY	621.00	-

Report Ref No. CC4/ASM21010338/R1ps3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER (CONSISTENT)	NOT NECESSARY	435.00	-
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	123.00	-
1	REAR ABSORBER LH (CONSISTENT)	NOT NECESSARY	377.00	-
1	REAR KNUCKLE BEARING LH (CONSISTENT)	NOT NECESSARY	298.00	-
1	REAR BEARING HUB LH (CONSISTENT)	NOT NECESSARY	315.00	-
1	REAR AXLE (CONSISTENT)	NOT NECESSARY	1,972.00	-
	LESS 25% DISCOUNT		-3,299.25	-866.50
			9,897.75	2,599.50
1	REAR RIM LH (SN)(CONSISTENT)	SCRATCHED	789.00	300.00
	LESS 25% DISCOUNT		-197.25	-
			591.75	300.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR INNER BOARD CLIPS (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT DOOR OUTER GARNISH CLIPS (SN)(CONSISTENT)	NECESSARY	100.00	30.00
1	FRONT DOOR VISOR LH (SN)(CONSISTENT)	NOT NECESSARY	300.00	-
1	REAR DOOR INNER BOARD CLIPS (SN)(CONSISTENT)	NECESSARY	100.00	40.00
1	REAR DOOR OUTER GARNISH CLIPS (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR DOOR VISOR LH (SN)(CONSISTENT)	NOT NECESSARY	300.00	-
1	SIDE SKIRT CLIPS (SN)(CONSISTENT)	NECESSARY	100.00	30.00
1	REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR FENDER COWLING CLIPS (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WHEEL PROTECTOR CLIPS (SN)(CONSISTENT)	NECESSARY	100.00	30.00
1	TAIL LAMP CLIPS (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR TYRE LH (SN)(CONSISTENT)	NOT NECESSARY	800.00	-
			2,400.00	130.00
<b><u>LABOUR</u></b>				
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT DOOR LH.		1,600.00	500.00
	SPRAY PAINT ON AFFECTED AREAS .		1,200.00	650.00
	TO RNR REAR WINDSCREEN .	NOT NECESSARY	400.00	-

Report Ref No. CC4/ASM21010338/R1ps3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND TAIL LAMP FUNCTION .	NOT NECESSARY	150.00	-
	TO RNR REAR INNER TRIM AND UPHOLSTERY .		400.00	60.00
	TO CHECK WHEEL ALIGNMENT AND ADJUST .		250.00	60.00
	TO RNR UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO CHECK WHEEL BALANCING .	NOT NECESSARY	250.00	-
	TO CHECK WATER LEAK .	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS.	NOT NECESSARY	600.00	-
	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION .	NOT NECESSARY	150.00	-
	TO PERFORM RUST PROOFING.	NOT NECESSARY	400.00	-
	TO RNR REAR AND FRONT DOOR MECHANISM .		600.00	100.00
			6,400.00	1,370.00
	<b>GRAND TOTAL</b>		<b>19,289.50</b>	<b>4,399.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,500.00</b>

Report Ref No. CC4/ASM21010338/R1ps3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.