



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 3319X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER -TOP (CONSISTENT)	TO REPAIR SEE LABOUR	1,250.20	-
2	FRONT BUMPER -LOWER (CONSISTENT)	DEFORMED	1,282.30	540.00
1	FRONT NUMBER PLATE (CONSISTENT)	CRACKED	50.00	50.00
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	DEFORMED	68.20	68.20
1	REAR BUMPER SIDE BRACKET (CONSISTENT)	NOT NECESSARY	125.30	-
	LESS 10% DISCOUNT		-	-65.82
			2,776.00	592.38
<b>LABOUR</b>				
	TO CHECK WIRING SYSTEM.		60.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER -TOP .		400.00	200.00
	SPRAY PAINTING.		500.00	250.00
			960.00	480.00
<b>GRAND TOTAL</b>			<b>3,736.00</b>	<b>1,072.38</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>850.00</b>

Report Ref No. CC4/ASM21010340/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.