

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21010341/EES3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SMT9157M	<b>Insured Vehicle No :</b>	SMA3476G
Date of Loss:	06/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004462

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMT9157M</b>	Engine No:	F7253534B48B20A
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBA5F32020FH99036
Reg. Date:	23/07/2020 (Man. Year: 2019)	Odometer:	27650 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,764.50	1,589.15	1,175.35	42.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,431.50</b>	<b>3,761.15</b>	<b>1,670.35</b>	<b>30.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	380.21	263.28	116.93	30.75
<b>Nett Amount (S\$)</b>	<b>5,811.71</b>	<b>4,024.43</b>	<b>1,787.28</b>	<b>30.75</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,331.88</b>		

INSPECTION

Date of Assignment:	07/10/2021	Performance Motors Limited (Alexandra)
Date Inspected:	26/10/2021 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	3.0 days	Singapore 159941

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
<b>Parts:</b>	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMT9157M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*TAILPIPE TRIM CHROME D=90MM	Not Necessary	125.85 FS	*- FS
3	1		*MOUNT LATERAL	Not Necessary	199.95 FS	*- FS
4	1		*REAR BUMPER CARRIER	Not Necessary	493.80 FS	*- FS
5	1		*TRIM STRIP (SPORT)	Cut	104.20 FS	*104.20 FS
6	1		*REAR RH TRIM PANEL	Cut	75.25 FS	*75.25 FS
7	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	134.30 FS	*- FS
8	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	134.30 FS	*- FS
9	1		*REAR BUMPER PANEL PRIMED (SP)	Dented	1,281.30 FS	*1,281.30 FS
10	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	48.10 FS	*- FS
11	1		*REAR RH REAR REFLECTOR	Not Necessary	39.05 FS	*- FS
12	1		*ADAPTER	Broken	48.40 FS	*48.40 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>2,764.50</b>	<b>1,589.15</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,667.00</b>	<b>2,172.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >