

ASS. REC. BY:

REF:

F02 / 210 10 340/kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 863k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lump Sum: 101 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/10 8 2325.72 Contin

Veh No: SLQ 3453AYr Regn: 0717Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hondac.c. 1496Colour: M. Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 48104

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru3

1247293

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Mod: NI / S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: _____

215/55R17

BS / DUN / EXNOVA / GYI / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 3/10/21D.O.I. 13/10/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Transportation: _____

S + RS. SI _____

Fees _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0027979
Hitachi Capital Asia Pacific Pte Ltd

Page 1 of 2
Your ref. TP-YN 3021A MS FC
Job No. 72273
Our ref. 21.10.05
Payment
Date 4/10/2021

Attn

Vehicle No SLQ 3453A
Vehicle Model Honda Vezel
Accident on 3/10/2021

*NOT Withclaim
Repairing B&Pain*

2325.72 4 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts					
1.00	Pc	Front bumper <i>762.70</i>	872.20	20.00	<i>Br/No</i> 697.76 ✓
1.00	Pc	Front bumper side retainer LH	18.70	20.00	<i>in</i> 14.96 X
1.00	Pc	Front bumper side retainer RH	18.70	20.00	<i>in</i> 14.96 X
10.00	Pcs	Front bumper lower clips	3.00	20.00	<i>in</i> 24.00 ✓
1.00	Pc	Front grille	308.90	20.00	<i>CM</i> 247.12 ✓
1.00	Pc	Front grille chrome moulding	360.80	20.00	<i>CM</i> 288.64 ✓
1.00	Pc	Front grille logo emblem	30.50	20.00	<i>in</i> 24.40 ✓
1.00	Pc	Front grille lower chrome moulding	96.50	20.00	<i>CM</i> 77.20 ✓
Special nett item					
1.00	Pc	Front number plate	35.00		<i>CM</i> 35.00 ✓
Labour & Misc					
1.00		To knock dents on front body, to straighten front body and renew of parts	350.00		<i>320h</i> 350.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的测量与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0027979
Hitachi Capital Asia Pacific Pte Ltd

Page 2 of 2
Your ref. TP-YN 3021A MS FC
Job No. 72273
Our ref. 21 10 05
Payment
Date 4/10/2021
Date 14/10/2021

Attn
Vehicle No SLQ 3453A
Vehicle Model Honda Vezel
Accident on 3/10/2021
Accident at 3/10/2021

② 2325.72

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00		To spray paint 767.70	450.00		450.00
1.00	Pk	Front bumper reinforcement	294.70	20.00	235.76
1.00	Pk	Front headlamp lower bracket RH	57.20	20.00	45.76
1.00	Pk	Front grille centre bracket	42.10	20.00	33.68

400%

Sub Total
Sub-Total 2,224.04
GST 7.00% 155.68
Total S\$ 2,379.72

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SUPPLEMENTARY ESTIMATE

EST. No EST0027979
Hitachi Capital Asia Pacific Pte Ltd

Page 1 of 1
Your ref. TP-YN 3021A MS FC
Job No. 72273
Our ref. 21.10.05
Payment
Date 14/10/2021

Attn

Vehicle No SLQ 3453A
Vehicle Model . Honda Vezel
Accident on ... 3/10/2021

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
SUPPLEMENTARY ITEM.					
1.00	Pc	Front bumper reinforcement	294.70	20.00	235.76
1.00	Pc	Front headlamp lower bracket RH	37.20	20.00	29.76
1.00	Pc	Front grille centre bracket	42.10	20.00	33.68

Sub-Total 299.20
GST 7.00% 20.94
Total S\$ 320.14

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."