

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21010345/RVY3E2

**Date:** 31/03/2022

### REFERENCE

Insured/Claimant: OOCL LOGISTICS (SINGAPORE) PTE. LIMITED Policy No: DMCVSNW00055752100  
Date of Loss: 04/10/2021 Nature of Claim: OD Claim No: SNM21D205674/C01/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG438K**  
Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2687584  
Reg. Date: 26/05/2017 (Man. Year: 2017) Chassis No: KDH2015026069  
Colour: White Odometer: 117145 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$57,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,181.00	15,539.00	4,642.00	23.00
Miscellaneous Items	250.00	150.00	100.00	40.00
Labour	2,281.72	2,443.80	-162.08	-7.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,712.72</b>	<b>18,132.80</b>	<b>4,579.92</b>	<b>20.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,500.00</b>		
<b>- Excess (S\$)</b>	0.00	350.00	-350.00	
<b>(S\$)</b>	22,712.72	14,150.00	8,562.72	37.70
<b>+ GST 7.00/7.00% (S\$)</b>	1,589.89	990.50	599.39	37.70
<b>Nett Amount (S\$)</b>	<b>24,302.61</b>	<b>15,140.50</b>	<b>9,162.11</b>	<b>37.70</b>

### INSPECTION

Date of Assignment: 07/10/2021 Present Location: Goldbell Engineering Pte Ltd (Tuas)  
Date Inspected: 08/10/2021 Inspected At: Goldbell Engineering Pte Ltd (Tuas)  
10 Tuas Ave 18  
Singapore 638894  
Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 31 Mar 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG438K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Total Parts</b>		14,936.00 F	*10,294.00 F
<b><u>Supplementary #1</u></b>						
2	1		<b>*CTR INST PANEL COVER</b>	Cracked	580.00 F	*580.00 F
3	1		<b>*AIR CONDITIONING</b>	Bent	610.00 F	*610.00 F
4	1		<b>*EVAPORATOR</b>	Bent	300.00 F	*300.00 F
5	1		<b>*SUPPORT SUB ASSY</b>	Bent	380.00 F	*380.00 F
6	1		<b>*HEAT EXCHANGER</b>	Bent	1,620.00 F	*1,620.00 F
7	1		<b>*AIR FILTER ASSY</b>	Cracked	680.00 F	*680.00 F
8	1		<b>*AIR FILTER ELEMENT</b>	Cut	250.00 F	*250.00 F
9	1		<b>*LOWER AIR FILTER COVER</b>	Cracked	100.00 F	*100.00 F
10	1		<b>*SUSPENS INTAKE HOSE</b>	Cracked	125.00 F	*125.00 F
11	1		<b>*BRAKE POWER CONTROL</b>	Bent	600.00 F	*600.00 F
					<b>Total Parts (\$\$)</b>	<b>20,181.00</b>
						<b>15,539.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Total Of Extras	250.00	150.00
Sub Total (\$\$)			250.00	150.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	1,310.40	1,570.80
2	Total Paint Including Material	New	721.32	623.00
<u>Supplementary #2</u>				
<u>Labour Items</u>				
3	BRAKE PEDAL SWITCH	New	100.00	100.00
<u>Supplementary #3</u>				
<u>Labour Items</u>				
4	REFILL AIR CON COOLANT	New	150.00	150.00
Gross Labour Cost (\$\$)			2,281.72	2,443.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >