6/27/22, 2:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI21010346/RTY3M4

3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Date: 27/06/2022

REFERENCE

Insured/Claimant: TIANG SOO HUA Policy No: DMPCSNW00197242000

Date of Loss: 25/09/2021 Nature of Claim: OD Claim No: SNM21D205488/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV7794M

Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGHU127649

Reg. Date: 16/01/2018 (Man. Year: 2017) Chassis No: KMHD841CMJU613240

Colour: Grey Odometer: 24609 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,078.80	1,411.00	2,667.80	65.41
Miscellaneous Items		270.00	80.00	190.00	70.37
Labour		281.40	105.00	176.40	62.69
Paintwork Labour		465.56	342.88	122.68	26.35
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,095.76	1,938.88	3,156.88	61.95
	- Excess (S\$)	500.00	0.00	500.00	100.00
	(S\$)	4,595.76	1,938.88	2,656.88	57.81
	+ GST 7.00/7.00% (S\$)	321.70	135.72	185.98	57.81
	Nett Amount (S\$)	4,917.46	2,074.60	2,842.86	57.81

INSPECTION

Date of Assignment: 07/10/2021 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 08/10/2021 Inspected At: 6 Marsiling Lane

Singapore 739145

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jun 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLV7794M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*PARTS		3,708.00 F	*1,411.00 F
F=Franchise part.				
		Sub Total (S\$)	3,708.00	1,411.00
	+ Margin	on L,N Items 10.00/0.00% (S\$)	370.80	0.00
		Total Parts (S\$)	4,078.80	1,411.00
		-		
	Repoi	t was unsubmitted during this print-ou	t.	

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			,
1 1 EXTRAS		270.00	80.00
	Sub Total (S\$)	270.00	80.00

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 LABOUR FOR SPRAY PAINTING	New	465.56	342.88
Labour Items			
2 LABOUR FOR PANEL BEATING	New	281.40	105.00
	Gross Labour Cost (S\$)	746.96	447.88

< END OF ESTIMATES >

Report was unsubmitted during this print-out.