

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21010354/BPA3Q2**Date:** 14/02/2022REFERENCE

|                              |                                       |                             |              |
|------------------------------|---------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D20MFL004551 |
| <b>Claimant Vehicle No :</b> | SLR7845X                              | <b>Insured Vehicle No :</b> | SMQ2718G     |
| Date of Loss:                | 30/09/2021                            | Nature of Claim:            | TP           |
|                              |                                       | Claim No:                   | N/A          |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | SLR7845X                          | Engine No:  | 2ZR8150401   |
| Make & Model:               | TOYOTA C-HR HYBRID, 1.8 S CVT (A) | Chassis No: | ZYX102056855 |
| Reg. Date:                  | 28/08/2017 (Man. Year: 2017)      | Odometer:   | 217970 km    |
| Colour:                     | Blue                              |             |              |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | Market Value/New Car Price        |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/55 R17    | Rear Tyre Size:  | 225/55 R17    |
| Front Left Side:  | Triangle 5 mm | Rear Left Side:  | Tourador 5 mm |
| Front Right Side: | Triangle 5 mm | Rear Right Side: | Tourador 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                       | 8,954.52          | 6,030.12          | 2,924.40          | 32.66         |
| Miscellaneous Items                                         | 0.00              | 0.00              | 0.00              |               |
| Labour                                                      | 4,600.00          | 1,880.00          | 2,720.00          | 59.13         |
| Paintwork Labour                                            | 0.00              | 0.00              | 0.00              |               |
| Towing                                                      | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>                         | <b>13,554.52</b>  | <b>7,910.12</b>   | <b>5,644.40</b>   | <b>41.64</b>  |
| <b>Approved Total (Overridden) (S\$)</b>                    |                   | <b>6,050.00</b>   |                   |               |
| <b>(S\$)</b>                                                | 13,554.52         | 6,050.00          | 7,504.52          | 55.37         |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 948.82            | 423.50            | 525.32            | 55.37         |
| <b>Nett Amount (S\$)</b>                                    | <b>14,503.34</b>  | <b>6,473.50</b>   | <b>8,029.84</b>   | <b>55.37</b>  |
| <b>+ Car Rental (9.0 x S\$120.00/day + 7.00% GST) (S\$)</b> |                   | 1,155.60          |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                               |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>7,636.55</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>                          |                   | <b>7,600.00</b>   |                   |               |

INSPECTION

|                             |                          |                                              |
|-----------------------------|--------------------------|----------------------------------------------|
| Date of Assignment:         | 07/10/2021               | Team Autopro Pte Ltd (sin Ming) (HQ)         |
| Date Inspected:             | 07/10/2021 Inspected At: | 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY |
| Estimated Period of Repair: | 8.0 days                 | Singapore 575722                             |

**Adjuster:** Lim Teow Guan**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 24 Nov 2021)

**Parts:** M1-SUV      TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLR7845X)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *TAILGATE                             | Dented        | 1,445.50 FL | *1,112.50 FL |
| 2   | 1   |          | *TAILGATE LOGO                        | Necessary     | 84.50 FL    | *72.20 FL    |
| 3   | 1   |          | *TAILGATE EMBLEM C-HR                 | Necessary     | 129.60 FL   | *55.60 FL    |
| 4   | 1   |          | *TAILGATE EMBLEM HYBRID SYNERGY DRIVE | Necessary     | 106.30 FL   | *65.70 FL    |
| 5   | 1   |          | *TAILGATE INNER LOCK                  | Jammed        | 364.50 FL   | *364.50 FL   |
| 6   | 1   |          | *TAILGATE INNER STRIKER               | Not Damaged   | 58.00 FL    | *- FL        |
| 7   | 1   |          | *TAILGATE INNER TRIM BOARD            | Broken        | 267.80 FL   | *267.80 FL   |
| 8   | 1   |          | *TAILGATE OUTER GARNISH               | Broken        | 978.10 FL   | *891.20 FL   |
| 9   | 1   |          | *TAILGATE LAMP RH                     | Broken        | 578.90 FL   | *353.50 FL   |
| 10  | 1   |          | *TAILGATE WINDSCREEN MOULDING         | Necessary     | 184.60 FL   | *133.70 FL   |
| 11  | 1   |          | *TAILGATE ANTENNA SENSOR              | Broken        | 198.30 FL   | *198.30 FL   |
| 12  | 1   |          | *REAR BUMPER                          | Broken        | 1,124.50 FL | *855.10 FL   |
| 13  | 1   |          | *REAR BUMPER LOWER LID                | Broken        | 465.00 FL   | *465.00 FL   |
| 14  | 1   |          | *REAR BUMPER LOWER LID CENTRE GARNISH | Broken        | 68.00 FL    | *68.00 FL    |
| 15  | 1   |          | *REAR BUMPER REINFORCEMENT            | Bent          | 578.90 FL   | *393.20 FL   |
| 16  | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary     | 136.00 FL   | *136.00 FL   |
| 17  | 2   |          | *REAR BUMPER BRACKET                  | Necessary     | 169.20 FL   | *169.20 FL   |
| 18  | 1   |          | *REAR BUMPER TOW COVER                | Broken        | 35.00 FL    | *35.00 FL    |
| 19  | 1   |          | *REAR BUMPER REFLECTOR RH             | Broken        | 218.00 FL   | *118.00 FL   |
| 20  | 1   |          | *REAR BUMPER REFLECTOR GARNISH RH     | Broken        | 135.00 FL   | *135.00 FL   |
| 21  | 1   |          | *REAR END PANEL                       | Dented        | 789.10 FL   | *716.00 FL   |
| 22  | 1   |          | *REAR END PANEL TOP GARNISH           | Not Damaged   | 285.70 FL   | *- FL        |
| 23  | 1   |          | *TAILLAMP RH                          | Broken        | 982.20 FL   | *768.00 FL   |
| 24  | 2   |          | *TAILLAMP LOWER BRACKET               | No such part  | 250.00 FL   | *- FL        |
| 25  | 1   |          | *TAILGATE SEALANT                     | Necessary     | 100.00 FS   | *40.00 FS    |
| 26  | 1   |          | *TAILGATE INNER TRIM BOARD CLIPS      | Necessary     | 50.00 FS    | *30.00 FS    |
| 27  | 1   |          | *TAILGATE OUTER GARNISH CLIPS         | Necessary     | 50.00 FS    | *20.00 FS    |
| 28  | 2   |          | *TAILGATE LAMP CLIPS                  | No such part  | 100.00 FS   | *- FS        |
| 29  | 1   |          | *TAILGATE LAMP SEAL                   | O/S Necessary | 120.00 FS   | *20.00 FS    |
| 30  | 1   |          | *TAILGATE WINDSCREEN SEALANT          | Necessary     | 100.00 FS   | *40.00 FS    |
| 31  | 1   |          | *TAILGATE WINDSCREEN INNER SEAL       | Necessary     | 60.00 FS    | *30.00 FS    |
| 32  | 1   |          | *TAILGATE WINDSCREEN RIMER & CLEANER  | Not Necessary | 80.00 FS    | *- FS        |
| 33  | 1   |          | *REAR BUMPER CLIPS                    | Necessary     | 50.00 FS    | *30.00 FS    |
| 34  | 1   |          | *REAR BUMPER LOWER LID CLIPS          | Necessary     | 50.00 FS    | *20.00 FS    |
| 35  | 2   |          | *REAR BUMPER REFLECTOR GARNISH CLIPS  | No such part  | 100.00 FS   | *- FS        |
| 36  | 1   |          | *REAR END PANEL SEALANT               | Necessary     | 100.00 FS   | *30.00 FS    |
| 37  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS     | Not Necessary | 50.00 FS    | *- FS        |
| 38  | 1   |          | *TAILLAMP CLIPS                       | O/S Necessary | 100.00 FS   | *20.00 FS    |
| 39  | 1   |          | *TAILLAMP SEAL                        | O/S Necessary | 120.00 FS   | *20.00 FS    |
| 40  | 2   |          | *REAR BUMPER REVERSE SENSOR           | Scratched     | 500.00 FS   | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>11,362.70</b> | <b>7,873.50</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 2,408.18         | 1,843.38        |
| <b>Total Parts (\$\$)</b>                                  | <b>8,954.52</b>  | <b>6,030.12</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                    | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                |          |                 |                 |
| 1                              | R&R TAILGATE COMPONENT         | New      | 150.00          | 80.00           |
| 2                              | R&R TAILGATE WINDSCREEN        | New      | 250.00          | 120.00          |
| 3                              | R&R REAR BUMPER REVERSE SENSOR | New      | 100.00          | 60.00           |
| 4                              | CHECK WIRING                   | New      | 100.00          | 20.00           |
| 5                              | UPHOLSTERY                     | New      | 300.00          | 0.00            |
| 6                              | DIAGNOSTIC RESET FAULT CODE    | New      | 300.00          | 0.00            |
| 7                              | PANEL BEATING                  | New      | 1,600.00        | 1,000.00        |
| 8                              | RUST PROOFING                  | New      | 200.00          | 0.00            |
| 9                              | SPRAY PAINTING                 | New      | 1,600.00        | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |                                |          | <b>4,600.00</b> | <b>1,880.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >