

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010355/ERA3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0001400_01
Claimant Vehicle No :	SKZ4041M	Insured Vehicle No :	PC5158R
Date of Loss:	05/10/2021	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ4041M	Engine No:	CXS258982
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)	Chassis No:	WVWZZZAUZFW357394
Reg. Date:	21/01/2016 (Man. Year: 2015)	Odometer:	73755 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	830.70	830.70	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	640.00	480.00	160.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,481.70	1,321.70	160.00	10.80
+ GST 7.00/7.00% (S\$)	103.72	92.52	11.20	10.80

Nett Amount (S\$)	1,585.42	1,414.22	171.20	10.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/10/2021	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	08/10/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2021)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ4041M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR GLASS RH	Broken	194.00 FL	*194.00 FL
2	1		*SIDE MIRROR COVER RH	Missing	154.00 FL	*154.00 FL
3	1		*SIDE MIRROR HOUSING RH	Broken	575.00 FL	*575.00 FL
4	1		*FRONT DOOR RH - REPAIR (NPA)	Repair	-	*- FL
					Sub Total (\$\$)	923.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	92.30
					Total Parts (\$\$)	830.70

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK & STRAIGHTEN ON FRONT DOOR RH.TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	New	280.00	200.00
2	TO INSPECT LIGHTING MECHANISM & CHECK WIRING	New	80.00	30.00
3	TO SPRAY PAINT ON REPAIRED AREAS	New	280.00	250.00
Gross Labour Cost (S\$)			640.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >