

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI21010359/Vvf3e2	
	36 ROBINSON RO SINGAPORE 0688		Date:	27/10/2021		
				Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 1049J	Veh. Inspected	d t	SMY 6209R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21002807MFCV	Excess (\$)		0.00	
	Assign From	SITHARA	Assign Date		08/10/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT 5008	c.c		1560	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	VF30E9HD8FS179624	Colour		GREY	
	Odometer	156328 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R16	GOODYEAR		7 mm	
	L/H Front Tyre	215/55 R16	GOODYEAR		7 mm	
	R/H Rear Tyre	215/55 R16	GOODYEAR		7 mm	
	L/H Rear Tyre	215/55 R16	GOODYEAR		7 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	22/09/2021	Inspect Date /	Time	12/10/2021 ( 09:30 AM )	
	Survey held at	Survey held at SIN SENG HONG SPRAY PAINTING & SERVICES				
	BLK 3022A UBI ROAD 1 #01-53 SINGAPORE 408716					
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$39,000.00					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/FCI21010359/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser