PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. PAS/TP/0330918

To: Mr Yeo Teck Meng C/o. 1 Kaki Bukit Ave 6 #01-43 Autobay Singapore 417883

Date of Report

: 05/11/2018

Date of Assignment

: 14/09/2018

Report requested by Date of Accident

: Mr Yeo Teck Meng : 13/09/2018

Date of Inspection

: 14/09/2018

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. Make & Model

: SFG7715S

: Honda Odyssey

: 07/01/2016 : Met. Grey

Engine Capacity (cc) : 2356cc

Mileage (km) Chassis / Frame No. : 66420km : JHMRC1890GC200982

Engine No.

: K24W72010298

TYRE CONDITION

Date of Registration

Colour

Front LH

: 6 mm

: Continental

Front RH

: 6 mm

Make

: Continental

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

Make

: Continental

Make

: Continental

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

Gereral Bodywork

: Good

Paintwork

: Good

Handbrake

Serviceable

Footbrake

Serviceable

Steering

Serviceable

Apparent Engine Modification

· Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. New Hock Teck Motor Workshop

1, Kaki Bukit Ave 6, #01-43, Autobay, Singapore 417883

ASSESSMENT

Repairer's Estimate

27,156.80 \$

Rev sed Amount

17,547.44 \$

Less Excess

\$

Recommended Reserve

15,790.00 (Lump Sum) : \$

Estimated Normal Period of Repairs

: 10 Working Days

Disclaimer: This report is intended for the exclusive use of the addresses solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



Correspondence Address 1 Simei St 3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email. pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No: SFG7715S

Report No.: PAS/TP/0330918

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. New Hock Teck Motor Workshop, 1, Kaki Bukit Ave 6, #01-43, Autobay, Singapore 417883.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, rear windscreen, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$17,547.44.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$15,790.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to tl e repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



Vehicle No.: SFG7715S

PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax. 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Report No.: PAS/TP/0330918

APPRAISEMENT SCHEDULE

S/No.		Qty	Parts Descriptions	Condition				airer's mate (S\$)	Our Assessment (S\$)		
								7 - 3			1395
	1	1 pc	Tailgate	Dented			\$	1,749.30	\$	1,749.30	
	2	1 pc	Tailgate hinge R/L	Bent/Repair			\$	80.80	\$	- 2	7.
	3	2 pcs	Tailgate stay support R/L	Refit	\$	205.80	\$	411.60	\$	40.80	/
	4	1 pc	Tailgate emblem (Logo)	Cracked/Necessary			\$	40.80	\$	325.90	
(5	1 pc	Tailgate center reflector	Dented/Cracked			\$	325.90	\$		1000
	6	2 pcs	- ' A . D/I	Cracked/Broken	\$	478.20	\$	956.40	\$	956.40 137.00 ×	. 02
	7	2 pcs	- 1. 1. D/I	Cracked	\$	68.50	\$	137.00	\$		1295
	8	I pc	Tailgate center chrome moulding	Cracked			\$	395.80	\$	395.80	
	9	1 pc	Tailgate auto lock motor	No such item			\$	389.20	\$		1,231
	10	1 pc	Tailgate lock	Dented/Jammed			\$	389.20	\$	389.20	/
	11	1 pc	Tailgate weatherstrip	Tom/Necessary			\$	215.40	\$	215.40	120
	12	1 pc	Tailgate inner trim	Dented/Deformed			\$	458.90	\$	458.90	/
	13	1 pc	Tailgate wiper blade	Tom			\$	110.50	\$	110.50	/
	14	1 pc	Tailgate wiper arm	Dented/Bent			\$	140.50	\$	140.50	/,
	15	1 pc	Tailgate wiper arm cover	Cracked			\$	41.70	\$	41.70	
	16	1 pc	Tailgate wiper arm motor	Dented/Damaged			\$	398.60	\$	398.60	1293
	17	1 pc	Tailgate windscreen	Broken/Shattered			\$	1,460.40	\$	1,460.40	/
			Tailgate windscreen inner seal	Necessary			\$	159.50	\$	159.50	/
	18	1 pc	Tailgate windscreen moulding T/B	Necessary	\$	82.30	\$	164.60	\$	164.60	/
	19	2 pcs	Tailgate windscreen moulding R/L	Necessary	\$	82.30	\$	164.60	\$	164.60	1666
	20		Taillamp R/L	Cracked/Broken	\$	1,021.80	\$	2,043.60	\$	2,043.60	0000
	21		Taillamp clip R/L	No such item	\$	8.00	\$	32.00	\$	- ^	/
	22		Taillamp lower cover R/L	LH Dented/Deformed	\$	325.30	\$	650.60	\$	325.30	/
	23	2 pcs	Taillamp lower cover bracket R/L	LH Cracked	\$	65.50	\$	131.00	\$	65.50	/
	24	200		Dented			\$	897.20	\$	897.20	
	25	1 pc	Rr bumper clip	Necessary	\$	6.50	\$	52.00	\$	52.00	/
	26		s Rr bumper retainer R/L	Cracked/Necessary	\$	88.50	\$	177.00	\$	177.00	,
	27			LH Cracked	\$	95.40	\$	190.80	\$	95.40	/
	28		Rr bumper reflector R/L Wee	Dented/Damaged			\$	235.80	\$	235.80	/
	29	l pc	Rr lock antenna	Dented/Cracked			\$	146.80	\$	146.80	¥ 1706
	30	l pc		Cracked/Deformed	\$	984.80	\$	1,969.60	\$	1,969.60	,
	31		s Rr fender inner trim R/L	Dented/Distorted	350		\$	851.20	\$	851.20	^
	32	l pc		Dented/Deformed			\$	225.80	\$	225.80 -	, .
	33	1 pc		Dented/Repair			\$	1,289.50	\$	- X	
	34	1 pc	Rr floor panel	Serviceable			\$	683.20	\$	- 7	
	35	1 pc	Rr floor panel trim	Dented/Damaged	\$	320.00	\$	1,280.00	2pcs \$	640.00	500
	36		s Rr bumper reverse sensor	Dented/Repair	4	# 10 To 10 T		(Refe	er labour no	5. 2, 8 & 9)	
	37		s Rr fender R/L	Dented/Repair				(Refe	er labour ne	5. 2, 8 & 9)	
	38	1 pc	Rr floor panel	Deliten/Kehan			0	19,046.80		15,034.30	
						D'	2	19,040.00	20% \$		
					Less	Discount:		19,046.80	The second second	12,027.44	

List Parts Sub-Total:



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St 3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email. pasvos@hotmail.com Business Reg. 201404434D

Wildlie, 5255 2254 F dr. 5722 5555				Report No.: PAS/TP/0330918					
Vehicle No. : SFG7715S S/No. Qty Parts Descriptions		Condition			Repairer's Estimate (S\$)		Our Assessment (S\$)		
/INU.	Qty	Tatts Descriptions					19,046.80		12,027.44
1 2 3 4	1 set 1 set 1 pc 2 pcs 1 pc	Camera Recorders Rr reverse camera Rr sealant (end panel & floor pan)	Dented Rr Cam missing Dented/Damaged Necessary Necessary		S/N S/N S/N S/N	\$ 50.00 \$ 850.00 \$ 680.00 \$ 450.00 \$ 50.00		\$ \$ \$ \$	50.00 850.00 680.00 80.00 40.00
5	1 pc	Rr windscreen sealant	Spe	ecial Nett Su	b-Total:	\$	2,080.00	\$	1,700.00
				Part	s Total :	\$	21,126.80	\$	13,727.44



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Address. 1 Simei St 3 #02-24 S(529890) Mobile: 9295 2204 Fax. 6722 8508 Email pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SFG7715S	mand (A. Verderich) von der ill son	Report No.: PAS/TP/0330918					
o. Labour Descriptions		epairer's stimate (S\$)	Our Assessment (S\$)				
1 To install rear windscreen to new tailgate.	\$	150.00	\$	120.00			
2 To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repair	s. \$	380.00	\$	159.00			
3 To remove, replace and reinstall rear reverse sensors & control unit.	\$	100.00	\$	60.00			
4 To remove, replace and reinstall rear reverse camera.	\$	380.00	\$	60.96			
5 To check rear electrical wiring system.	\$	100.00	\$	60,60			
6 Towing.	\$	100.00	\$	80.00			
7 To spray anti-rust coating on new and affected panels.	\$	150.00	\$	90.00			
8 To straighten, repair, realign on affected area and replace damaged parts.	\$	2,400.00	\$	1,500.00			
9 To spray painting, blending on affected and adjacent area.	\$	2,000.00	\$	1,500.00			
10 To transfer tailgate component parts to new tailgate.	\$	150.00	\$	120.00			
11 To vacuum, clean up broken glass debris and cleaning service rear interior trim & seat leathers.	\$	120.00	\$	80.00			
Labour Total:	\$	6,030.00	\$	3,820.00			
Total (Parts & Labour) :	\$	27,156.80	\$	17,547.44			
	7	total: 13	3120.0	8			
cor Lump Sum Repairs	,	1. 10	cr.	O			
The final adjusted Lump Sum contract amount is \$ 15,790.00		43: 10.51					
Under normal circumstances, the repairs should be completed within a reasonable period of 10 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and a		07	vays.				

151 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OFM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner. entire satisfaction of owner. the Repairer of the following: To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Companie not approved by Repairer fied to the company within 7 days from the date hereof. Note: The revised estimate has been adjusted from a Otherwise this revised amount shall be deemed as valid.

Date:

Page 5 of 5