

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010363/AVY3N2**Date:** 08/12/2021**REFERENCE**

Insured/Claimant: MOK CHENG HAO @ RAPHAEL ELIJAH
Date of Loss: 05/10/2021

Policy No: 7210058191
Nature of Claim: OD Claim No: 0032755271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA2870X**
Make & Model: AUDI A3 SPORTBACK, 1.4 TFSI (A) Engine No: DFY267218
Reg. Date: 15/06/2021 (Man. Year: 2021) Chassis No: WAUZZZGY7MA095411
Colour: Red Odometer: 3834 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$142,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,954.00	4,396.08	8,557.92	66.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,342.00	2,660.00	53.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,956.00	6,738.08	11,217.92	62.47
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	17,556.00	6,338.08	11,217.92	63.90
+ GST 7.00/7.00% (S\$)	1,228.92	443.67	785.25	63.90
Nett Amount (S\$)	18,784.92	6,781.75	12,003.17	63.90

INSPECTION

Date of Assignment: 08/10/2021

Date Inspected: 07/10/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,574.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	281.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	116.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE	Cracked	387.00 FS	*309.60 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-CENTER	Not Necessary	237.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	60.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Repair	292.00 FS	*- FS
8	1		*FRONT BUMPER COVER TRIM-RH	Cut	93.00 FS	*74.08 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	153.00 FS	*- FS
10	1		*FRONT BUMPER SUPPORT-RH	Not Necessary	38.00 FS	*- FS
11	1		*FRONT RADIATOR GRILLE	Cracked	842.00 FS	*673.20 FS
12	1		*FRONT RADIATOR CLOSING ELEMENT	Cracked	152.00 FS	*121.60 FS
13	1		*FRONT REINFORCEMENT FILLER FOAM	Cracked	107.00 FS	*85.60 FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	703.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	82.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	18.00 FS	*- FS
17	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
18	1		*AIR-CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
19	1		*HORN	Not Necessary	145.00 FS	*- FS
20	1		*HORN BRACKET-RH	Not Necessary	31.00 FS	*- FS
21	1		*FRONT BONNET	Repair	2,664.00 FS	*- FS
22	1		*FRONT BONNET IMPACT PROTECTION	Not Necessary	27.00 FS	*- FS
23	1		*FRONT BONNET STRIKER-RH	Not Necessary	110.00 FS	*- FS
24	1		*FRONT BONNET LOCK	Not Necessary	214.00 FS	*- FS
25	1		*FRONT HEADLIGHT-RH	Cut	3,840.00 FS	*3,072.00 FS
26	1		*FRONT HEADLIGHT CYLINDER	Not Necessary	193.00 FS	*- FS
27	1		*FRONT HEADLIGHT WASHER HOSE	Not Necessary	93.00 FS	*- FS
28	1		*FRONT RADIATOR AIR GUIDE-RH	Not Necessary	36.00 FS	*- FS
29	1		*FRONT RADIATOR AIR GUIDE-CENTER	Not Necessary	52.00 FS	*- FS
30	1		*FRONT RADIATOR SEAL	Not Necessary	13.00 FS	*- FS
31	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
32	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
33	1		*FRONT TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **12,954.00** **4,396.08**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,400.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	2,342.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >