#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21010366/AQY3E2

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 10/03/2022

**REFERENCE** 

Insured/Claimant: D'CRUZ JOANNA NIRMALA Policy No: 7210026381

Date of Loss: 27/09/2021 Nature of Claim: OD Claim No: 9966733108SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJN2611G

Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC25704

Reg. Date: 19/03/2021 (Man. Year: 2020) Chassis No: WAUZZZF35M1068777

Colour: Grey Odometer: 9597 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$160,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                              | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts               |                              | 4,603.00   | 2,857.36   | 1,745.64   | 37.92  |
| Miscellaneous Items |                              | 0.00       | 0.00       | 0.00       |        |
| Labour              |                              | 4,072.00   | 1,522.00   | 2,550.00   | 62.62  |
| Paintwork Labour    |                              | 0.00       | 0.00       | 0.00       |        |
| Towing              |                              | 0.00       | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$) | 8,675.00   | 4,379.36   | 4,295.64   | 49.52  |
|                     | - Excess (S\$)               | 800.00     | 800.00     | 0.00       | 0.00   |
|                     | (S\$)                        | 7,875.00   | 3,579.36   | 4,295.64   | 54.55  |
|                     | + GST 7.00/7.00% (S\$)       | 551.25     | 250.56     | 300.69     | 54.55  |
|                     | Nett Amount (S\$)            | 8,426.25   | 3,829.92   | 4,596.33   | 54.55  |

INSPECTION

Date of Assignment: 08/10/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

Date Inspected: 07/10/2021 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

# **Recommended Parts**

| No.   | Qty Part No.                                  | Particulars                      | Condition         | Repairer's  | Amount       |  |  |
|-------|---|----------------------------------|-------------------|-------------|--------------|--|--|
| 1     | 1   | *REAR DOOR - RH                  | Dented            | 2,909.00 FS | *2,327.20 FS |  |  |
| 2     | 1   | *REAR DOOR OUTER SEAL - RH       | Necessary         | 135.00 FS   | *108.00 FS   |  |  |
| 3     | 1   | *REAR DOOR ATTACHMENT PARTS - RH | Not Necessary     | 311.00 FS   | *- FS        |  |  |
| 4     | 1   | *REAR DOOR CATCH - RH            | Not Necessary     | 120.00 FS   | *- FS        |  |  |
| 5     | 1   | *REAR DOOR SILL PANEL - RH       | Not Necessary     | 135.00 FS   | *-FS         |  |  |
| 6     | 1   | *REAR DOOR COVER - RH            | Deformed          | 257.00 FS   | *205.20 FS   |  |  |
| 7     | 1   | *REAR WHEEL COVER - RH           | Cut               | 268.00 FS   | *214.40 FS   |  |  |
| 8     | 1   | *REAR DOOR WHEEL COVER - RH      | Not Necessary     | 268.00 FS   | *-FS         |  |  |
| 9     | 1   | *SUNDRIES                        | Necessary         | 200.00 FS   | *2.56 FS     |  |  |
| F=Fra | anchise part. S=SpcN                          | ett.                             | _                 |             |              |  |  |
|       |   |                                  | Total Parts (S\$) | 4,603.00    | 2,857.36     |  |  |
|       | Report was unsubmitted during this print-out. |                                  |                   |             |              |  |  |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

| No         | Particulars   | Lab.Type   | Repairer's | Amount   |
|------------|---|------------|------------|----------|
| <u>Lab</u> | our Items   |            |            |          |
| 1          | TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES                                   | New        | 400.00     | 280.00   |
| 2          | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR | New        | 280.00     | 0.00     |
| 3          | TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED                              | New        | 1,200.00   | 500.00   |
| 4          | TO RESRAY RHS REAR DOOR AND RHS FRONT DOOR  | New        | 2,000.00   | 550.00   |
| 5          | TO CARRY OUT DIAGNOSTIC CHECK   | New        | 192.00     | 192.00   |
|            | Gross Labour Cost (S\$)   |            | 4,072.00   | 1,522.00 |
|            | Report was unsubmitted during this  | print-out. |            |          |

< END OF ESTIMATES >