

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21010367/AQY3E2

**Date:** 26/01/2022

### REFERENCE

Insured/Claimant:	TAN YI QIANG NICHOLAS	Policy No:	2100472638-05	
Date of Loss:	05/10/2021	Nature of Claim:	OD	Claim No: 9870457592SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9321B		
Make & Model:	AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)	Engine No:	CHZ093498
Reg. Date:	30/06/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8X2GB103256
Colour:	Blue	Odometer:	52946 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R16	Rear Tyre Size:	215/45 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,896.00	4,008.24	10,887.76	73.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,852.00	2,292.00	6,560.00	74.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,748.00</b>	<b>6,300.24</b>	<b>17,447.76</b>	<b>73.47</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>23,148.00</b>	<b>5,700.24</b>	<b>17,447.76</b>	<b>75.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,620.36</b>	<b>399.02</b>	<b>1,221.34</b>	<b>75.37</b>
<b>Nett Amount (S\$)</b>	<b>24,768.36</b>	<b>6,099.26</b>	<b>18,669.10</b>	<b>75.37</b>

### INSPECTION

Date of Assignment:	08/10/2021		
Date Inspected:	07/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,634.00 FS	*1,307.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	248.00 FS	*- FS
3	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
6	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	808.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	970.00 FS	*775.60 FS
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	723.00 FS	*- FS
9	1		*FRONT BUMPER BRACKET	Not Necessary	19.00 FS	*- FS
10	2		*HORN - LH / RH	Not Necessary	452.00 FS	*- FS
11	1		*BONNET	Dented	2,261.00 FS	*1,808.80 FS
12	1		*BONNET ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
13	1		*BONNET EDGE PROTECTION	Necessary	20.00 FS	*15.92 FS
14	1		*BONNET UPPER CATCH	Not Necessary	66.00 FS	*- FS
15	2		*BONNET STRIKER	Not Necessary	100.00 FS	*- FS
16	1		*BONNET LOWER CATCH	Not Necessary	63.00 FS	*- FS
17	2		*BONNET LOCK	Not Necessary	427.00 FS	*- FS
18	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
19	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
20	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	236.00 FS	*- FS
21	2		*HEADLIGHT - LH / RH	Not Necessary	3,906.00 FS	*- FS
22	1		*A/C STICKER	Necessary	38.00 FS	*29.84 FS
23	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
24	1		*LOCK CARRIER	Not Necessary	1,024.00 FS	*- FS
25	1		*A/C CONDENSER	Not Necessary	551.00 FS	*- FS
26	6		*COOLANT	Not Necessary	142.00 FS	*- FS
27	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	62.00 FS	*- FS
28	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
29	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
30	1		*FRONT BUMPER FORM PIECE	Not Necessary	118.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,896.00 4,008.24

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,852.00</b>	<b>2,292.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >