

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21010368/Eqy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	13/10/2021	
	ATTN: CHAN KIAN	CHUAN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 4019R	Veh. Inspected	k	SMX 7076E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03JKD	Excess (\$)		0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date		08/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MR2B23F3X01165000	Colour		SILVER	
	Odometer	36922 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/55 R15	DUNLOP		4 mm	
	L/H Front Tyre	185/55 R15	DUNLOP		4 mm	
	R/H Rear Tyre	185/55 R15	DUNLOP		4 mm	
	L/H Rear Tyre	185/55 R15	DUNLOP		4 mm	
4. Description of Damages						
	THE VEHICLE SUSPORTION.	JSTAINED DAMAGES AT THE FRONT AND REAR				
5.	General Information					
	Accident Date	07/10/2021	Inspect Date /	Time	08/10/2021 (03:50 PM)	
	Survey held at 7 PENJURU CLOSE S608779					
	Repairer	Repairer VFIX AUTO SERVICE PTE LTD				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000-\$13,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 18 Working Days					

Report Ref No. CS3/ASM21010368/Eqy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser