### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

From: LKK Auto Consultants Pte Ltd 4 Shenton Way 51 Ubi Ave 1 #01-25 #21-01 SGX Centre 2 Paya Ubi Industrial Park Singapore 068807 Singapore 408933

Attn: 14 Oct 2021 Christina Wong Date:

## **Preliminary Advice**

Insured Vehicle No : FBM9126U

TP Vehicle No : GBH8451M : 06/10/2021 Accident Date Make : TOYOTA HIACE Assignment Date : 08/10/2021

Date of Inspection : 12/10/2021 Est. Duration of Repair

Inspection At : LIM YEW BOO SPRAY PAINT CO (HQ)

BLK 10 SIN MING INDUSTRIAL ESTATE, #01-10

SINGAPORE 575645

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,578.95
Revised Amount	:S\$	4,336.00
Check Items (Estimated)	:S\$	595.05
Total	:S\$	4,931.05

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 56,000.00 COE / PARF Rebate 19,932.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 36,068.00

#### Remarks

(	)	The vehicle is economical for repair
(	)	The vehicle is not economical for repair
(	)	Part-by-Part repair
(	)	Lump Sum repair

The above survey was conducted on a 'without prejudice' basis. ( X )

Please note that the preliminary advice amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.