

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21010377/ETF3E2

Date: 27/10/2021

REFERENCE

Insured/Claimant: ABDUR RASHEED BIN ABDUL BUHARI
Date of Loss: 07/10/2021

Policy No: 2070137828
Nature of Claim: OD Claim No: 9686407546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2732M	Engine No:	G4FGKH752958
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416ML5064085
Reg. Date:	24/09/2020 (Man. Year: 2019)	Odometer:	21056 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$83,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,115.00	2,362.40	2,752.60	53.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	2,800.00	2,240.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,155.00	5,162.40	4,992.60	49.16
+ GST 7.00/7.00% (S\$)	710.85	361.37	349.48	49.16
Nett Amount (S\$)	10,865.85	5,523.77	5,342.08	49.16

INSPECTION

Date of Assignment: 08/10/2021

Date Inspected: 08/10/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens,
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	4		*PARKING SENSOR	Not Necessary	800.00 FS	-
4	1		*COVER-RR BUMPER	Broken	651.00 F	*651.00 FL
5	1		*COVER-RR BUMPER LWR	Broken	241.00 F	*241.00 FL
6	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	88.00 F	*88.00 FL
7	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	88.00 F	*- FL
8	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 F	*- FL
9	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 F	*- FL
10	1		*BRACKET-RR BEAM UPR MTG, RH	Broken	9.00 F	*9.00 FL
11	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 F	*- FL
12	1		*BEAM-RR BUMPER	Broken	318.00 F	*318.00 FL
13	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 F	*6.00 FL
14	1		*BRACKET-RR BEAM LWR MTG	Not Necessary	6.00 F	*6.00 FL
15	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 F	*- FL
16	1		*STAY-RR BUMPER RH	Bent	65.00 F	*65.00 FL
17	1		*STAY-RR BUMPER LH	Bent	65.00 F	*65.00 FL
18	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 F	*- FL
19	1		*BRACKET-ASSY RR BPR SIDE UPR, R	Not Necessary	31.00 F	*- FL
20	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 F	*1,297.00 FL
21	1		*PANEL ASSY-BACK	Repair	324.00 F	*- FL
22	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 F	*- FL
23	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 F	*- FL
24	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 F	*- FL
25	1		*EMBLEM-CERATO	Necessary	28.00 F	*28.00 FL
26	1		*EMBLEM-GT LINE	Necessary	45.00 F	*45.00 FL
27	1		*LOGO ASSY-KIA SUB	Not Necessary	32.00 F	*- FL
28	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 F	*- FL
29	1		*CLIPS (10PCS) (Supplementary)	Necessary	20.00 F	*20.00 FL
30	1		*COVER-RR BUMPER UNDER,LH (Supplementary)	Broken	33.00 F	*33.00 FL
31	1		*BRACKET-RR BEAM LWR MTG (Supplementary)	Broken	6.00 F	*6.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,115.00	2,938.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	575.60
Total Parts (\$\$)	5,115.00	2,362.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, BOOTLID, REAR END PANEL, REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH	New	1,600.00	800.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
4	SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH	New	2,100.00	700.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
8	REPAIR REAR END PANEL AND CHASSIS RH (Supplementary)	New	400.00	400.00
9	SPRAY PAINT REAR END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$)			5,040.00	2,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >