

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI21010378/UTF3N2**Date:** 29/11/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SKC5634S **Insured Vehicle No :** GBF6710P
 Date of Loss: 22/08/2021 Nature of Claim: TP Claim No: CDMCG21001614

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC5634S**
 Make & Model: MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A) Engine No: P520725663
 Reg. Date: 24/02/2021 (Man. Year: 2021) Chassis No: JM6BP2SAAM1107036
 Colour: Black Odometer: 13748 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R18 Rear Tyre Size: 215/45R18
 Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
 Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,005.20	2,534.80	3,470.40	57.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,900.00	3,210.00	3,690.00	53.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,905.20	5,744.80	7,160.40	55.48
+ GST 7.00/7.00% (S\$)	903.36	402.14	501.22	55.48
Nett Amount (S\$)	13,808.56	6,146.94	7,661.62	55.48

INSPECTION

Date of Assignment: 08/10/2021
 Date Inspected: 08/11/2021 Inspected At: Eurokars Services Pte Ltd (ubi) (HQ)
 5 UBI CLOSE
 Singapore 408605
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2021)**Parts:** 143 MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKC5634S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	997.40 FS	*997.40 FS
2	1		*BRACKET CENTER REAR BUMPER	Not Necessary	5.40 FS	*- FS
3	1		*REINF,REAR BUMPER	Not Necessary	541.70 FS	*- FS
4	1		*RETAINER RH REAR	Not Necessary	33.20 FS	*- FS
5	1		*RETAINER LH REAR	Not Necessary	33.20 FS	*- FS
6	4		*GROMMET,SCREW	Necessary	10.80 FS	*10.80 FS
7	1		*PLATE SET RR BUMPER	Not Necessary	213.80 FS	*- FS
8	1		*STAY,RR BUMPER	Not Necessary	91.90 FS	*- FS
9	1		*COVER,UNDE	Not Necessary	63.20 FS	*- FS
10	8		*FASTENER	Necessary	24.00 FS	*24.00 FS
11	3		*TAPE,PROTECTOR	Necessary	14.10 FS	*14.10 FS
12	2		*BRACKET,B/SENSOR BP	Necessary	46.80 FS	*46.80 FS
13	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 FS	*25.10 FS
14	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 FS	*25.10 FS
15	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 FS	*25.10 FS
16	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 FS	*25.10 FS
17	1		*RETAINER S.S ULTRASONIC	Necessary	61.30 FS	*61.30 FS
18	1		*RETAINER S.S ULTRASONIC	Necessary	61.30 FS	*61.30 FS
19	2		*SENSOR FRT BUMPER BP	Not Necessary	380.00 FS	*- FS
20	2		*LAMP,LICENSE	Not Necessary	230.00 FS	*- FS
21	1		*CAMERA BACK MONITOR	Serviceable	1,066.80 FS	*- FS
22	1		*TRUNK LID	Dented	896.00 FS	*896.00 FS
23	1		*WEATHERSTRIP TRK LID	Not Necessary	84.70 FS	*- FS
24	3		*COVER,HOLE	Necessary	7.50 FS	*7.50 FS
25	1		*HINGE LH TRUNK LID	Not Necessary	185.10 FS	*- FS
26	1		*HINGE RH TRUNK LID	Not Necessary	185.10 FS	*- FS
27	2		*GASKET,LAMP-LIFT GATE	Necessary	39.60 FS	*39.60 FS
28	2		*FASTENER	Necessary	12.40 FS	*12.40 FS
29	6		*GROMMET,SCREW-R,COMB	Necessary	19.80 FS	*19.80 FS
30	1		*GROMMET MAZDA 3	Necessary	34.60 FS	*34.60 FS
31	1		*GROMMET SKYACTIV	Necessary	42.50 FS	*42.50 FS
32	1		*MASCOT,REAR	Not Necessary	326.30 FS	*- FS
33	1		*EMBLEM M-HYBRID	Necessary	36.70 FS	*36.70 FS
34	11		*FASTENER	Necessary	39.60 FS	*39.60 FS
35	1		*NUMBER PLATE	Cracked	70.00 FS	*70.00 FS
36	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,005.20	2,534.80
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND TRUNK LID.TO REPAIR REAR END PANEL	New	2,640.00	1,320.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,TRUNK LID AND REAR END PANEL	New	3,150.00	1,260.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	180.00
4	TO TRANSFER REVERSE CAMERA	New	330.00	180.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	150.00
Gross Labour Cost (\$\$)			6,900.00	3,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >