

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121010380/UUF3N2**Date:** 18/10/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBJ9285J **Insured Vehicle No :** YQ436R

Date of Loss: 06/10/2021 Nature of Claim: TP Claim No: CDMCG21001952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ9285J**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEK (CBU) (M) Engine No: 4P10D26207

Reg. Date: 15/10/2019 (Man. Year: 2018) Chassis No: FEA01BA30055

Colour: White Odometer: 32755 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15 (D)

Front Left Side: Austone 7 mm Rear Left Side: Austone 7/7 mm

Front Right Side: Austone 7 mm Rear Right Side: Austone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,672.60	6,373.54	6,299.06	49.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,780.00	680.00	27.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,132.60	8,153.54	6,979.06	46.12
Approved Total (Overridden) (\$\$)		6,500.00		
(\$\$)	15,132.60	6,500.00	8,632.60	57.05
+ GST 7.00/7.00% (\$\$)	1,059.28	455.00	604.28	57.05
Nett Amount (\$\$)	16,191.88	6,955.00	9,236.88	57.05

INSPECTION

Date of Assignment: 08/10/2021

Date Inspected: 08/10/2021 Inspected At: Liu's Brother Auto Workshop (HQ)
1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Oct 2021)		
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEA01BR1SDEK (CBU) (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBJ9285J)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,127.60 F	*- FL
2	1		*FRONT BUMPER SIDE N/S	Deformed/Torn	441.70 F	*319.82 FL
3	1		*SET FRONT BUMPER SIDE CLIPS	Not Necessary	65.00 F	*- FL
4	1		*FRONT PANEL	Badly Dented	2,436.60 F	*1,660.58 FL
5	1		*FRONT WIPER PANEL	Cracked	1,482.10 F	*589.23 FL
6	1		*FRONT CORNER PANEL N/S	Cracked	486.90 F	*486.90 FL
7	1		*SET FRONT CORNER PANEL CLIPS	Not Necessary	28.00 F	*- FL
8	1		*FRONT GRILLE	Cracked	1,043.00 F	*785.21 FL
9	1		*SET FRONT GRILLE CLIPS	Necessary	80.00 F	*35.00 FL
10	1		*FRONT MITSUBISHI LOGO MOTIF	Necessary	186.80 F	*65.00 FL
11	1		*FRONT CANTER EMBLEM	Necessary	75.40 F	*75.40 FL
12	1		*FRONT FUSO EMBLEM	Necessary	163.80 F	*89.00 FL
13	1		*FRONT MIRROR ARM N/S	Cracked	545.20 F	*472.39 FL
14	1		*FRONT SIDE MIRROR ROUND N/S	Cracked	110.50 F	*110.50 FL
15	1		*FRONT SIDE MIRROR SQUARE N/S	Not Necessary	110.50 F	*- FL
16	1		*FRONT HEAD LAMP N/S	Cracked	856.40 F	*492.21 FL
17	1		*FRONT SIGNAL LAMP N/S	Cracked	324.30 F	*208.02 FL
18	1		*FRONT HEATER UNIT ASSY	Cracked	2,623.15 F	*2,623.15 FL
19	1		*FRONT AIRCON DISCHARGE HOSE	Dented/Bent	485.65 F	*485.65 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	12,672.60	8,498.06
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	2,124.52
Total Parts (S\$)	12,672.60	6,373.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL DASHBOARD,METER INSTRUMENTS,DISCONNECT WIRING & ETCS	New	400.00	250.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	680.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,000.00	700.00
5	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	100.00	100.00
6	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
Gross Labour Cost (\$\$)			2,460.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >