

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21010381/VTF3N2**Date:** 21/10/2021REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHA1012J **Insured Vehicle No :** SJW4213L

Date of Loss: 06/10/2021 Nature of Claim: TP Claim No: DMPC2100354H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA1012J**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDFU596606

Reg. Date: 10/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085523

Colour: Blue Odometer: 531134 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 206/60R16 Rear Tyre Size: 206/60R16

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,692.66	9,678.34	2,014.32	17.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	2,490.00	270.00	9.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,452.66	12,168.34	2,284.32	15.81
Approved Total (Overridden) (S\$)		9,700.00		
(S\$)	14,452.66	9,700.00	4,752.66	32.88
+ GST 7.00/7.00% (S\$)	1,011.69	679.00	332.69	32.88
Nett Amount (S\$)	15,464.35	10,379.00	5,085.35	32.88

INSPECTION

Date of Assignment: 08/10/2021

Date Inspected: 08/10/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1012J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID COVER	Deformed	2,609.80 FL	*2,609.80 FL
2	1		*BOOTLID HINGE LH	Shifted	142.30 FL	*142.30 FL
3	1		*BOOTLID HINGE RH	Shifted	142.30 FL	*142.30 FL
4	1		*BOOTLID LOCK	Bent	114.90 FL	*114.90 FL
5	1		*BOOTLID EMBLEM-H	Necessary	63.10 FL	*63.10 FL
6	1		*BOOTLID EMBLEM-CRDI	Necessary	52.40 FL	*52.40 FL
7	1		*BOOTLID EMBLEM-I40	Necessary	67.90 FL	*67.90 FL
8	1		*TAILLAMP ASSY RH	Cracked	697.80 FL	*697.80 FL
9	1		*TAILLAMP ASSY LH	Cracked	697.80 FL	*697.80 FL
10	1		*REAR BUMPER ASSY	Cut	553.00 FL	*553.00 FL
11	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	428.40 FL	*428.40 FL
13	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	1		*BUMPER REINFORCEMENT BRACKET LH	Serviceable	160.60 FL	*- FL
15	1		*BUMPER REINFORCEMENT BRACKET RH	Serviceable	160.60 FL	*- FL
16	1		*REAR BUMPER SPONGE	Cut	119.50 FL	*119.50 FL
17	1		*BOOTLID MOULDING	Necessary	85.00 FL	*85.00 FL
18	1		*BOOTLID LOWER GARNISH	Deformed	227.90 FL	*227.90 FL
19	1		*BOOTLID LAMP LH	Serviceable	622.20 FL	*- FL
20	1		*BOOTLID LAMP RH	Serviceable	622.20 FL	*- FL
21	1		*REAR BUMPER REFLECTOR RH	Scratched	32.00 FL	*32.00 FL
22	1		*REAR END PANEL	Dented	526.70 FL	*526.70 FL
23	1		*REAR END PANEL GARNISH	Serviceable	57.70 FL	*- FL
24	1		*REAR FENDER RH	Deformed	2,171.40 FL	*2,171.40 FL
25	1		*SPARE TYRE PANEL	Repair	852.80 FL	*- FL
26	1		*REAR BUMPER SIDE BRACKET LH	Necessary	35.60 FL	*35.60 FL
27	1		*SPARE TYRE LOCK NUT	Serviceable	41.80 FL	*- FL
28	1		*EXHAUST PIPE RH	Bent	1,935.40 FL	*1,935.40 FL
29	1		*EXHAUST PIPE CENTRE	Bent	730.10 FL	*730.10 FL
30	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
31	2		*WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
32	1		*BOOTLID COMFORT LOGO	Necessary	30.00 FS	*30.00 FS
33	1		*BOOTLID TEL NOS LOGO	Necessary	30.00 FS	*30.00 FS
34	1		*BOOTLID APPS LOGO	Necessary	40.00 FS	*40.00 FS
35	1		*REVERSE SENSOR	Cut	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,532.90	12,015.00
- List Item Discount on L Items 20.00/20.00% (S\$)	2,840.24	2,336.66
Total Parts (S\$)	11,692.66	9,678.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	1,120.00
2	SPRAY PAINT	New	1,000.00	1,000.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	80.00	20.00
7	TOWING FEE	New	60.00	60.00
8	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
9	RENEW EXHAUST PIPE ASSY	New	120.00	120.00
Gross Labour Cost (S\$)			2,760.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >