

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21010383/ETF3E2

**Date:** 28/01/2022

### REFERENCE

Insured/Claimant:	ANG YU ANN	Policy No:	7210117588		
Date of Loss:	07/10/2021	Nature of Claim:	OD	Claim No:	4718571787SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC1674S</b>		
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LFMP173906
Reg. Date:	30/09/2021 (Man. Year: 2021)	Chassis No:	KNAD6817VN6611137
Colour:	Silver	Odometer:	102 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,520.00	2,404.80	2,115.20	46.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,560.00	460.00	22.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,540.00</b>	<b>3,964.80</b>	<b>2,575.20</b>	<b>39.38</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,940.00</b>	<b>3,364.80</b>	<b>2,575.20</b>	<b>43.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>415.80</b>	<b>235.54</b>	<b>180.26</b>	<b>43.35</b>
<b>Nett Amount (S\$)</b>	<b>6,355.80</b>	<b>3,600.34</b>	<b>2,755.46</b>	<b>43.35</b>

### INSPECTION

Date of Assignment:	08/10/2021	
Date Inspected:	08/10/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Broken	295.00 F	*295.00 FL
3	1		*GRILLE ASSY-RADIATOR	Cut	324.00 F	*324.00 FL
4	1		*COVER-FR BUMPER, LWR	Cut	367.00 F	*367.00 FL
5	1		*SKID PLATE-FR BUMPER	Crushed	55.00 F	*55.00 FL
6	1		*GRILLE-FRONT BUMPER	Broken	247.00 F	*247.00 FL
7	1		*STRIP-FR BUMPER	Not Necessary	27.00 F	*- FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 F	*98.00 FL
9	1		*STIFFNER-FR BPR LWR	Broken	123.00 F	*123.00 FL
10	1		*WIRING HARNESS-FR BUMPER	Not Necessary	150.00 F	*- FL
11	1		*CONDENSER ASSY-COOLER	Dented	648.00 F	*648.00 FL
12	1		*AIR GUIDE	Not Necessary	52.00 F	*- FL
13	1		*RADIATOR ASSY	Not Necessary	696.00 F	*- FL
14	1		*COOLER ASSY-INTER	Not Necessary	564.00 F	*- FL
15	1		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	177.00 F	*177.00 FL
16	1		*LIP-FR BUMPER	Cut	42.00 F	*42.00 FL
			(Supplementary)			
17	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 F	*61.00 FL
			(Supplementary)			
18	1		*BEAM-COMPLETE-FR BUMPER	Dented	544.00 F	*544.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,520.00	3,001.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	596.20
Total Parts (\$\$)	4,520.00	2,404.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER & AFFECTED AREA	New	800.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL & BONNET	New	700.00	700.00
3	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	60.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
7	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
8	TO TOP UP AIRCON GAS	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,020.00</b>	<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >