5/31/22, 8:25 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21010387/UGA3Q2

31/05/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210062078 **Claimant Vehicle**

SLJ9800D Insured Vehicle No: GBJ7305Z No:

Date of Loss: 07/10/2021 Nature of Claim: TP Claim No: 6847527561SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ9800D**

PORSCHE 911 CARRERA S, 3.8 PDK (991 Series) Make & Model: Engine No: C03548

01/03/2012 (Man. Year: 2011) Chassis No: WP0ZZZ99ZCS112019 Reg. Date:

133001 km Colour: Black Odometer:

Engine Capacity: 3800 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20 Rear Tyre Size: 295/30Z R20 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,174.00	3,285.00	1,889.00	36.51
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,740.00	3,500.00	1,240.00	26.16
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	9,914.00	6,785.00	3,129.00	31.56
	+ GST 7.00/7.00% (S\$)	693.98	474.95	219.03	31.56
	Nett Amount (S\$)	10,607.98	7,259.95	3,348.03	31.56
	+ Loss of Use (5.0 x S	\$120.00/day) (S\$)	600.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	7,861.95		
	Global Sui	m Settlement (S\$)	7,800.00		

INSPECTION

Date of Assignment: 15/10/2021

Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Inspected At: Date Inspected: 15/10/2021

Singapore 408711

Estimated Period of Repair: 4.0 days

MARCUS CHUA Manager: Chong Pui Lin Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Torn	3,550.00 F	*3,550.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 F	*100.00 FL
3	2		*FRONT BUMPER SENSOR (CENTRE)	Serviceable	814.00 F	*- FL
4	2		*FRONT BUMPER SENSOR GASKET	Not Necessary	30.00 F	*- FL
5	1		*FRONT BUMPER SIGNAL LAMP RH	Not Necessary	180.00 F	*- FL
6	1		*FRONT BONNET EMBLEM (LOGO)	Not Necessary	400.00 F	*- FL
7	1		*FRONT NUMBER PLATE	Not Necessary	100.00 FS	*- FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,174.00	3,650.00
			- List Item Discount on	L Items 0.00/10.00% (S\$)	0.00	365.00
				Total Parts (S\$)	5,174.00	3,285.00
			Report was unsubmitted du	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT ,RENEW ,KNOCKING & WELDING FRONT BONNET ,REMOVE & INSTALL ALL DAMAGE PARTS STRAIGHTEN & REALIGN BODY	New	1,080.00	750.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	1,200.00	700.00
3	REMOVE & REFIX FRONT BUMPER SENSOR	New	100.00	50.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	80.00	20.00
5	BODY STICKER ON DAMAGE PARTS	New	1,900.00	1,900.00
6	DIAGNOSTIC CHECK & RESET	New	380.00	80.00
	Gross L	abour Cost (S\$)	4,740.00	3,500.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >