

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010389/VTF3E2

Date: 28/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070142044
Claimant Vehicle No : SJA5824H Insured Vehicle No : YP77Z
Date of Loss: 06/10/2021 Nature of Claim: TP Claim No: 8027382090SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA5824H**
Make & Model: TOYOTA VIOS E, 1.5 (A) Engine No: 1NZX660329
Reg. Date: 14/12/2007 (Man. Year: 2007) Chassis No: MR053HY9305039670
Colour: Silver Odometer: 268526 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,611.18	1,923.71	5,687.47	74.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,550.00	1,350.00	46.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,511.18	3,473.71	7,037.47	66.95
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	10,511.18	2,800.00	7,711.18	73.36

INSPECTION

Date of Assignment: 11/10/2021
Date Inspected: 11/10/2021 Inspected At: Yk Supreme Autoworks (HQ)
1 KAKI BUKIT AVENUE 6# 01-22 AUTOBAY
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	423.13 F	*423.13 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	28.90 F	*20.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	76.80 F	*76.80 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	322.60 F	*282.10 FL
5	1		*FRONT BUMPER LOGO	Necessary	48.20 F	*48.20 FL
6	1		*FRONT BUMPER FOG LAMP	Serviceable	221.60 F	*- FL
7	1		*FRONT BUMPER FOG LAMP GARNISH	Serviceable	98.70 F	*- FL
8	1		*BONNET	Repair	696.90 F	*- FL
9	2		*BONNET HINGE	Serviceable	119.00 F	*- FL
10	1		*HEADLAMP LH	Cracked / Split	1,015.60 F	*398.70 FL
11	1		*FRONT FENDER	Dented	597.40 F	*388.50 FL
12	1		*FRONT FENDER INNERSHIELD	Folded / Torn	154.20 F	*100.00 FL
13	1		*SET FRONT FENDER INNERSHIELD CLIPS	Necessary	26.40 F	*20.00 FL
14	1		*FRONT FENDER BADGE	Necessary	35.50 F	*35.50 FL
15	1		*SIDE VIEW MIRROR	Damaged	977.60 F	*325.35 FL
16	1		*FRONT DOOR PANEL	Repair	1,045.00 F	*- FL
17	1		*FRONT DOOR WEATHERSTRIP	Serviceable	148.00 F	*- FL
18	2		*FRONT DOOR HINGE	Serviceable	148.00 F	*- FL
19	1		*SET FRONT DOOR TRIM BOARD CLIP	Necessary	26.80 F	*20.00 FL
20	1		*FRONT SHOCK ABSORBER	Serviceable	349.25 F	*- FL
21	1		*FRONT LOWER ARM	Serviceable	364.00 F	*- FL
22	1		*FRONT WHEEL BEARING	Serviceable	117.60 F	*- FL
23	1		*FRONT WHEEL RIM	Scratched	380.00 FS	*320.00 FS
24	1		*FRONT TYRE	Serviceable	190.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,611.18	2,458.28
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	534.57
Total Parts (S\$)	7,611.18	1,923.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	80.00	50.00
2	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS	New	100.00	20.00
3	TO REMOVE AND REPLACE FRONT SUSPENSION COMPONENTS. TO REALIGN REPLACEMENT PARTS	New	250.00	0.00
4	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	1,000.00	600.00
5	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,100.00	800.00
6	TO CARRY OUT ALL WHEEL ALIGNMENT AND TO RESET SETTINGS WHERE NECESSARY TO SPECIFICATIONS	New	120.00	60.00
7	TO REMOVE AND TRANSFER DOOR FITTINGS AND ATTACHMENTS. TO CHECK FOR PROPER FUNCTIONS	New	100.00	0.00
8	TO CARRY OUT ANTI RUST TREATMENT	New	150.00	20.00
Gross Labour Cost (\$\$)			2,900.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >