

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION RE	PORT			
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21010394/Avf3e2		
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	19/10/2021		
				Code:	SMO		
1.	. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	FBL 2494H	Veh. Inspected	b	SGK 8118B		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	CMTD2103019/SYH	Excess (\$)		0.00		
	Assign From	GRACE TEO	Assign Date		11/10/2021		
2.	Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALPHARD	c.c		2493		
	Engine No.	HIDDEN	Year of Reg.		2015		
	Chassis No.	AGH300020343	Colour		WHITE		
	Odometer	194748 KM	Steering		IN ORDER		
	Brakes	IN ORDER	Modification		SPORTS RIM		
	General	GOOD					
3. Conditions of Tyres							
		Size	Make		Balance		
	R/H Front Tyre	235/50 R18	BRIDGESTONE		6 mm		
	L/H Front Tyre	235/50 R18	BRIDGESTONE		6 mm		
	R/H Rear Tyre	235/50 R18	BRIDGESTONE		6 mm		
	L/H Rear Tyre	235/50 R18	BRIDGESTONE		6 mm		
4.	Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.						
5.	5. General Information						
	Accident Date	08/10/2021	Inspect Date /	Time	11/10/2021 (12:30 PM)		
	Survey held at	SPEEDWERKZ PTE LTD					
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807						
	Remarks						
5a.			A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000-\$13,000				
5a.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTEI /AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	O AT THE TIME O TIMATE. PHOTOGRAPHS	F INSPE	CTION.		
5a. 5b.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTEI /AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE ED REPAIR COST OF THE DAMA	O AT THE TIME O TIMATE. PHOTOGRAPHS	F INSPE	CTION.		

Report Ref No. CS3/SMO21010394/Avf3e2

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.